OKLAHOMA DEPARTMENT	T OF TRANSP	PORTAT	ION			Inspection	_	
NBI No.: 14437 Structure No.: 3625 090	00 X Local I	ID:-1		Suii. F	Rating: ND	/3.1	Health Index: 83.1	
Description: <u>IDENTIFICATION</u>					INSPE	ECTION		
30'-55'-55'-30' CONT. CONC SLAB SPANS W/ 1.5' SAFETY	CURBS	Type In	sp Req.	Insp Done	Freq:	Insp. Date:	Next Insp.:	
1. State: Oklahoma 2. SHD District: Divis		NBI:		Y	24	11/13/2017	11/13/2019	
3. County Code: KAY 4. Place Code: Unknown Admin. Area: Unknown	11	FC Freq.: UW Freq.:	N N	N N	NA NA	NA NA	NA NA	
5. Inventory Route (Route On Structure): 1 - 4 - 1 - E0200) - 0	OS Freq.:	N	N	NA	NA NA	NA NA	
6. Feature Intersected: I-35 UNDER					CLASSIF	FICATION		
7. Facility Carried: CO. RD. E0200 CO. RD. E020 9. Location: 9. MI N NOBLE C/L 11. Mile		12. Base Hwy	Network:			20. Toll Facility: 3 On 1	ree road	
13. LRS Inv. Route./ Subroute.: -1		21. Custodian:			-	22. Owner: 01 State Hig		
	itude: 097 20 46.02	26. Functional 100. Defense I		-		37. Historical Sig.: 5 No. 101. Parallel Structure:		
•	r Br. #: Unknown	102. Dir. of Tr				103. Temp. Structure: No	·	
STRUCTURE TYPE AND MATERIA 43. Main Span Material and Design Type	ALS	104. Highway				105. Fed. Land Hwy 0 N		
Concrete Continuous Slab		110. National	ruck Netv	Vork:) Not pa	art of na	112. NBIS Length: Long	g Enougn	
 Approach Span Material and Design Type Not Applicable (P) Not Applicable (I 	2)					<u>DITION</u>		
45. No. of Spans Main Unit: 4 46. No. of Approach S		58. Deck: 5 I 62. Culvert:			-	Satisfactory 60. S Channel Protection: N N	ub.: 6 Satisfactory	
107. Deck Type: 1 Concrete-Cast-in-Place108A. Wearing Surface: 0 None		Flowline Not		01.	Chamici	Channel Protection. 14 1	//(IVDI)	
108B. Membrane: 0 None								
108C. Deck Protection: None								
AGE AND SERVICE				LOAD	RATING	AND POSTING		
27. Year Built: 1959 106. Year Recons		31. Design Lo				41. Posting status: A O	·	
	9. Detour Length: 2.0 mi 9. Truck ADT %: 10	63. Op. Ratin 64. Operating			actor-Ton	Alt. Op. Rating Meth.: 30.0 41.0	1 LF Load Factor-To 69.2	
42A. Type of Service on: 1 Highway	79. Huck AD1 /0. 10	66. Inventory				14.9 18.6	-1.1	
42B. Type of Service under: 1 Highway		· ·				Alt. Inv. Rating Meth.: 1	1	
		70. Posting: 5	At/Above	Legal Loads		Date Rated: 12/11/20	07	
GEOMETRIC DATA 10. Inv. Rte. Min. Vert. Clr.: 328.1 ft				PROF	POSED IN	MPROVEMENTS		
32. Approach Roadway Width (W/ Shoulders): 20.3 ft		94. Bridge Cost: \$688,846 75. Type of Work: 31 Repl-Load Capacit 95. Roadway Cost: \$1,136,596 76. Lgth. of Improvment: 275.6 ft						
Deck Area: 4,983.7 sq. ft 33. Median: 0 N		96. Total Cost: \$1,928,769 114. Future ADT: 80						
34. Skew: 0 35. Structure Flare 47. Inv. Rte. Total Horiz. Clr.: 24.0 ft	d: 0 No flare	97. Year of C	Cost Est.:	2015		115. Year of Future AI	OT: 2035	
48. Length Maximum Span: 55.1 ft 49. Structure Len	ngth: 171.9 ft					TION DATA		
	lk Width R: 1.5 ft	 38. Navigat 39. Vertical 		l: NA-no wa : 0.0 ft	terway	40. Horizontal Cleara	nce: 0.0 ft	
51. Width Curb to Curb: 24.0 ft 52. Width Out to	Out: 29.0 ft	l		ot Applicable	(P)	116. Lift Bridge Vert. 0		
53. Minimum Vertical Clearance Over Bridge: 328.1 ft 54A/54B. Min. Vert. Underclearance: H Hwy beneath struct	16.8 ft					RAISAL		
<u>N/E</u> <u>S/W</u>		36A. Bridge					0 Substandard	
<u>Meas.</u> N1611 N1700 -1 S1610	S1702 -1	36B. Transit 67. Str. Eva		ostandard Above Min T		66D. Approach Rail Ends 68. Deck Geometry: 6		
Post. DO NOT U DO NOT U DO NOT U	DIV. 4 -1	l		ertical and Ho	orizontal:	•		
55A/55B. Minimum Lateral Undrclearance R: H Hwy beneath s	truct 9.7 ft	l	-	cy: N Not ap ent: 8 Equal I		Cris		
56. Minimum Lateral Undrclearance L: 18.9 ft				Not Over Wa		CIII		
200c. Temperature: 54 21	4a. Posted Weight Limit:	NR				. Girder Spacing/Number	-1.0 / -1	
200d. Weather: CLOUDY	b. Posted Speed Limit :	NR			244	. Span Lengths :		
201. Structural Steel ASTM Desig.: -1	c. Narrow/One Lane Bridged. Vertical Clearance Sign:	sign : NO YES				30 30 55 -1	-1 -1	
202. Waterproof Membrane :-1 Date Installed : 1/1/1901	Advanced Warning Sign:					55 -1		
203. Type Exp. Dev. : _						. Girder Depth : -1.000		
-	e. Navigation Lights :					. Type of Overlay : Overlay Thickness : 0		
204. Type of Handrail: BC 205. Material and Quantity: -1.0	Working/Not Working :	_			246	. Overlay Date : 1/	1/1901	
208. Type of Abutment : Skeleton	5. Overpass: A - Interstate				- 1	Overlay Depth Change		
Type of Foundation : Concrete Fining	 Substructure Cond. (U/W) Fill over RCB: 	: - -1			247	. Protective Systems : 1: _ 3:	l	
209. Type of Fiet / Found I Fiet _	2. Fill over RCB: 3. Appr. Slab/Rdwy Cond.:	Good			4:	_ 5:	_	
210 Foundation Fley -1.0 -1.0		XY	1. 1			. No. of Field Splices w/		
9680.0 9655.0 -1.0 22	5. Paint Type : Overcoat :	Not Appl Not Appl				. Scour Crit. POA exists? . Culvert Headwall Dist.		
	6. Date Painted:	-1						
1,1,1,01	7. Paint Coloring: 3. Deck Forming: Convention	-1				. Chan. Profile Up/Dowr a. OkiePROS Auto. Truc		
-1 -1 -1	Deck Forming: Convention	_			258	. Plans w/ found. are in f	ile at ODOT:	
23	8. School Bus Rte: Current a		te			. Scour Eval. is in file at		
24	0. Appr. Roadway Type: Grav	vC1				 Interchange at Intersect Interstate Milepoint: 	ion: No Interchange 216.73	

Page 1 of 2 1/4/2018

OKLAHOMA DEPARTMENT OF TRANSPORTATION -

Agency:

Bridge Inspection Report Suff. Rating: 73.1

Health Index:

NBI No.: 14437 Structure No.: 3625 0900 X Local ID:-1 ND 83.1 11/13/2017 Reported By: **GHINES** Inspection Date: Inspected With: Gary Richardson Invoice No.: -1

Structure / Inspection Notes

Maximum horizontal clearance below: N.B.= 45.6', S.B.=44' due to cable barriers & crash barrels.

G Hines inspection comments - 11/13/2017

PX - Each side drain is settled & broken at the top with a cavity developing under the SW slopewall edge & at the NW * PX - The West slopewall is settled with an abutment cavity & exposed piles - the East slopewall is separated at the center joint with undermining * Safety below = 1111 * Good gravel roadway above * FX - All OM-3's are in place but lean out *

Elm.	Env.	Description	Un.	Qty.	Qty.St. 1	% 1	Qty.St. 2	% 2	Qty.St. 3	% 3	Qty.St. 4	% 4	Qty.St. 5	% 5
38	4	Reinforced Concrete Slab	(SF)	4,126	0	0 %	4,126	100 %	0	0 %	0	0 %	0	0 %
205	4	Reinforced Conc Column or Pile Extension	(EA)	11	9	82 %	2	18 %	0	0 %	0	0 %	0	0 %
215	4	Reinforced Conc Abutment	(LF)	62	57	92 %	5	8 %	0	0 %	0	0 %	0	0 %
234	4	Reinforced Conc Cap	(LF)	81	45	56 %	36	44 %	0	0 %	0	0 %	0	0 %
310	4	Elastomeric Bearing	(EA)	5	5	100 %	0	0 %	0	0 %	0	0 %	0	0 %
331	4	Reinforced Conc Bridge Railing	(LF)	344	326	95 %	5	1 %	13	4 %	0	0 %	0	0 %
859	4	Soffit of Concrete Decks and Slabs	(EA)	1	0	0 %	1	100 %	0	0 %	0	0 %	0	0 %
958	4	Concrete Cracking	(EA)	1	0	0 %	0	0 %	0	0 %	1	100 %	0	0 %
967	4	Substructure Trafic Impact	(EA)	1	0	0 %	1	100 %	0	0 %	0	0 %	0	0 %
968	4	Erosion	(EA)	1	1	100 %	0	0 %	0	0 %	0	0 %	0	0 %

Additional

Elements

Elem.		Element Notes (Include Siz	e and Location of Det	erioration						
	PX - Some minor wear & grader scrapes noted in the wheel lanes. Light to moderate pattern & longitudal cracks of medium density are present in the wheel lanes - most are less than 1 foot apart. The soffit has cracking & discoloration in each span from 10% to 70% (35% avg). Soil & gravel need cleaned from the curb & gutter area.									
	One moderate chipped area noted on the lower NE the West abutment and one under the East abutmen		aling at the ground line on	the 2nd column. The total qu	antity includes 7 exposed piles under					
215	Minor defects & stains noted on each abutment.									
234	Some minor staining & popouts from rebar chairs of	n the bottom of each cap on each en	d. Minor defects noted at	the South end of bent #2. Goo	od condition overall					
310	< none >									
331	Superficial weathering overall. There are two posts	with spalling on the very tops. Some	e exposed rebar noted in se	cattered areas due to insuffici	ent cover.					
	59 Some light to moderate pattern cracking & discoloration is present in each span. 10% of span #1, 35% of span #2, 70% of span #3 (2009 photo), & 25% of span #4 has distress. No spalling noted.									
958										
967	One moderate chipped area noted on the lower NE area of the 1st column.									
968	PX - The West slopewall has settled full width expo	osing 7 piles up to 6 inches (includin	g wing piles). One pile is	barely visible on the East. Ne	eeds attention soon.					
Road	way Name : I-35 UNDER	NBI Information Applicable To T	he Route Under The Str	ucture						
5. Inv	ventory Route (Route Under Structure: 2 - 1	- 1 - 00035 - 0		102. Traffic Dir.:	2 2-way traffic					
10. M	in. Vert. Clr.(ft.): 16.8	28b. Lanes Und.:	4	104. Highway System:	1 On the NHS					
12. B	ase Hwy Network : On Base Network	29. ADT :	15700	105. Fed Land Hwy:	0 N/A (NBI)					
13. Ll	RS Inv. Rt./ Subroute: 3625 W0000 / 02	32. Appr. Roadway Width (ft.):	74.5	109. Truck ADT%:	36					
19. D	etour Len.(Mi.): 0.0	47. Total Horiz. Clr.(ft.):	45.6	110. Natl. Truck Network:	1 Part of natl network					
20. To	oll Facility: 3 On free road	51. Roadway Width (ft.):	74.5	114. Future ADT:	25120					
26. Fu	nction Class.: 01 Rural Interstate	100. Defense Highway:	1 On Interstate STRAH	NET						
Agency Field: 1.(Under Rte.): U 2.(Vert. X-Ref.): -1 3.(Compass Dir.): N 4.(Vert. Post. Inc.): 1608 5.(Vert. Post. Dec.): 1609										

1/4/2018 Page 2 of 2