

Oklahoma Dept. of Transportation - Bridge Inspection Report

NBI No.: 04085	Structure No.: 0902 0000 X	Local ID: -1	Suff. Rating: 21.10	SD
--------------------------	--------------------------------------	------------------------	-------------------------------	-----------

<p>Bridge Description: IDENTIFICATION</p> <div style="border: 1px solid black; padding: 2px;">38-100ft. PONY TRUSS & 2-36ft. I-BM. SPANS(BRIDGEPORT BR.)</div> <p>1. State: Oklahoma 2. Division: Division 4 3. County: CANADIAN 4. City: Unknown Admin Area: L/T Truss 5a. On/Under: Route On Structure 5b. Kind of Hwy: U.S. Hwy 5c. Lvl of Svc: Mainline 5d. Route No.: 00281 5e. Dir. Sufx: N/A (NBI)</p> <p>7. Facility Carried : U.S. 281 6. Feat. Intersect: S. CANADIAN RIVER 9. Location: CADDO CANADIAN CL 11. Mile Post: NA 13. LRS Inv. / Sub Rte: 0902 0000 / 01 16. Latitude: 35° 32' 25.00" 17. Longitude: 098° 19' 22.00" 98. Border Brdg: Unknown (P) % Responsible: 0.00 99. Border Brdg #: Unknown</p>	<p style="text-align: center;">INSPECTION</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Type</th> <th>Insp. Req.</th> <th>Insp. Done</th> <th>Freq.</th> <th>Insp. Date</th> <th>Next Insp.</th> </tr> </thead> <tbody> <tr> <td>NBI:</td> <td></td> <td>1</td> <td>12 months</td> <td>10/14/2018</td> <td>10/14/2019</td> </tr> <tr> <td>FC:</td> <td>Y</td> <td>1</td> <td>12 months</td> <td>10/14/2018</td> <td>10/14/2019</td> </tr> <tr> <td>UW:</td> <td>N</td> <td>0</td> <td></td> <td>NA</td> <td>NA</td> </tr> <tr> <td>OS:</td> <td>Y</td> <td>0</td> <td>12 months</td> <td>4/11/2018</td> <td>4/14/2019</td> </tr> </tbody> </table> <p style="text-align: center;">CLASSIFICATION</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>12. Base Hwy Net.: On Base Network</td> <td>101. Parallel Str.: No bridge exists</td> </tr> <tr> <td>20. Toll Facility: On free road</td> <td>102. Traffic Dir.: 2-way traffic</td> </tr> <tr> <td>21. Custodian: State</td> <td>103. Temp. Str.: Not Applicable (P)</td> </tr> <tr> <td>22. Owner: State</td> <td>104. Hwy System: Not on NHS</td> </tr> <tr> <td>26. Function Class: 06 Rural Minor Arterial</td> <td>105. Fed Land Hwy: N/A (NBI)</td> </tr> <tr> <td>37. Historical Sig.: Br eligible for NHRP</td> <td>110. Defense Hwy: Not a STRAHNET hwy</td> </tr> <tr> <td>100. Def. Hwy: Not a STRAHNET hwy</td> <td>112. NBIS Length: Long Enough</td> </tr> </table>	Type	Insp. Req.	Insp. Done	Freq.	Insp. Date	Next Insp.	NBI:		1	12 months	10/14/2018	10/14/2019	FC:	Y	1	12 months	10/14/2018	10/14/2019	UW:	N	0		NA	NA	OS:	Y	0	12 months	4/11/2018	4/14/2019	12. Base Hwy Net.: On Base Network	101. Parallel Str.: No bridge exists	20. Toll Facility: On free road	102. Traffic Dir.: 2-way traffic	21. Custodian: State	103. Temp. Str.: Not Applicable (P)	22. Owner: State	104. Hwy System: Not on NHS	26. Function Class: 06 Rural Minor Arterial	105. Fed Land Hwy: N/A (NBI)	37. Historical Sig.: Br eligible for NHRP	110. Defense Hwy: Not a STRAHNET hwy	100. Def. Hwy: Not a STRAHNET hwy	112. NBIS Length: Long Enough
Type	Insp. Req.	Insp. Done	Freq.	Insp. Date	Next Insp.																																								
NBI:		1	12 months	10/14/2018	10/14/2019																																								
FC:	Y	1	12 months	10/14/2018	10/14/2019																																								
UW:	N	0		NA	NA																																								
OS:	Y	0	12 months	4/11/2018	4/14/2019																																								
12. Base Hwy Net.: On Base Network	101. Parallel Str.: No bridge exists																																												
20. Toll Facility: On free road	102. Traffic Dir.: 2-way traffic																																												
21. Custodian: State	103. Temp. Str.: Not Applicable (P)																																												
22. Owner: State	104. Hwy System: Not on NHS																																												
26. Function Class: 06 Rural Minor Arterial	105. Fed Land Hwy: N/A (NBI)																																												
37. Historical Sig.: Br eligible for NHRP	110. Defense Hwy: Not a STRAHNET hwy																																												
100. Def. Hwy: Not a STRAHNET hwy	112. NBIS Length: Long Enough																																												

<p style="text-align: center;">STRUCTURE TYPE AND MATERIALS</p> <p>43a/b. Main Span: Steel / Truss-Thru 44a/b. Appr. Span: Steel / Stringer/Girder 45. # of Main Spans: 38 46. # of Appr. Spans: 2 107. Deck Type: Concrete-Cast-in-Place 108a. Wearing Surface: Bituminous 108b. Membrane: Unknown 108c. Deck protection: Unknown</p>	<p style="text-align: center;">CONDITION</p> <p>58. Deck: 5 Fair 59. Sup.: 4 Poor 60. Sub: 5 Fair 62. Culvert: N/A (NBI) 61. Chan./Chan. Prot.: 5 Bank Prot Eroded</p> <p>Flowline Notes</p> <div style="border: 1px solid black; padding: 2px;">OCT-2018: Flow too high to measure. Channel now in span 11. OCT-2017: 29.7' TOC at L4, west truss, span 10</div>
---	---

<p style="text-align: center;">AGE AND SERVICE</p> <p>19. Detour Length: 11.8 mi 27. Year Built: 1933 28a/b. Lanes on/und: 2 / 0 29. ADT: 1,100 30. Year of ADT: 2016 42a/b. Type of Svc on/und: Highway / Waterway</p> <p>106. Year Reconst.: 109. Truck ADT: 16%</p>	<p style="text-align: center;">LOAD RATING AND POSTING</p> <p>31. Design Load: M 13.5 (H 15) 41. Post. Status: P Posted for load 70. Posting: 2 20.0-29.9% below 63. Op / 65. Inv. Rating Meth.: 1 LF Load Factor / 1 LF Load Factor</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th>H</th> <th>HS</th> <th>3-3</th> <th>EV3</th> <th>SHV</th> </tr> </thead> <tbody> <tr> <td>64. Operating Rating (tons):</td> <td>15.00</td> <td>15.10</td> <td>65.40</td> <td>36.30</td> <td>0.00</td> </tr> <tr> <td>66. Inventory Rating (tons):</td> <td>14.00</td> <td>14.10</td> <td>37.70</td> <td>21.80</td> <td></td> </tr> </tbody> </table> <p style="text-align: right;">Date Rated: 03/25/2014</p>		H	HS	3-3	EV3	SHV	64. Operating Rating (tons):	15.00	15.10	65.40	36.30	0.00	66. Inventory Rating (tons):	14.00	14.10	37.70	21.80	
	H	HS	3-3	EV3	SHV														
64. Operating Rating (tons):	15.00	15.10	65.40	36.30	0.00														
66. Inventory Rating (tons):	14.00	14.10	37.70	21.80															

<p style="text-align: center;">GEOMETRIC DATA</p> <p>10. Vert. Clearance: 99.99 ft 32. Appr Rwy Width: 30.00 ft 33. Median: No median 34. Skew: 0.00° 35. Struct. Flared: No flare 47. Horizontal Clr: 24.00 ft 48. Length Max Span: 100.07 ft 49. Struct. Length: 3,937.01 ft</p> <p>50a. Curb/Sdwk Width L: 1.00 ft 50b. Curb/Sdwk Width R: 1.00 ft 51. Width Curb to Curb: 24.00 ft 52. Width Out to Out: 26.00 ft Deck Area: 102,364.79 sq. ft 53. Min. Vert. Cl. Ovr Brg: 99.99 ft 54a. Min. Vert. Undclr. Ref.: N Feature not hwy c 54b. Min. Vert. Undclr.: 0.00 ft 55a. Min. Lat. Undclr. Ref.: N Feature not hwy 55. Min. Lat. Underclr. R: 99.90 ft 56. Min. Lat. Underclr. L: 99.90 ft</p>	<p style="text-align: center;">APPRAISAL</p> <p>36a. Brdg Rail: 0 Substandard 36b. Transition: 0 Substandard 36c. Appr. Rail: 0 Substandard 36d. Appr. Rail Ends: 0 Substandard 67. Str Evaluation: 4 Minimum Tolerab</p> <p>68. Deck Geom.: 4 Tolerable 69. Vert./Horiz. Undclr: Not applicable (NB) 71. Waterway Adeq: 5 Above Tolerable 72. Appr. Alignment: 6 Equal Min Criteria 113. Scour Critical: 7 Countermeasures</p>
--	--

<p style="text-align: center;">OKLAHOMA ITEMS</p> <p>200c. Temperature: 50 200d. Weather: Rain/Snow 201. Struc. Stl. ASTM Desig.: -1 / -1 202. Waterprf. Membrane: -1 Date Installed: 01/01/1901 203. Type Exp. Device: Sliding Plate Open Joint-No Device 204. Type of Railing: Metal Railing (other) 205. Material Quantity: 10.00 208a. Type of Abutment: Pedestal b. Type of Found.: Bears on Natural Found. 209. Type of Pier/Found.: 2 / Yes No Piling/Drilled Shaft 210. Foundation Elev.: -1.00 -1.00 -1.00 -1.00 -1.00 211. Wear. Surf. Prot. Sys: None Date Installed: 01/01/1901 213. Utilities Attached: Communication</p>	<p style="text-align: center;">PROPOSED IMPROVEMENTS</p> <p>94. Bridge Cost: \$6,781,689 95. Roadway Cost: \$4,500,000 96. Total Cost: \$11,920,275 97. Yr. of Cost Est.: 2015</p> <p>75. Type of Work: 31 Repl-Load Capacity 76. Lngth of Improvement: 3,937.0 ft 114. Future ADT: 1,760 115. Yr. of Future ADT: 2036</p>
---	---

<p style="text-align: center;">NAVIGATION DATA</p> <p>38. Nav. Control: Permit Not Required 39. Vert. Clearance: 0.0 ft 40. Horiz. Clearance: 0.0 ft</p>	<p>111. Pier Protect.: 1 Not Required 116. Lift Bridge Vert. Clr.: 0.0 ft</p>
---	---

<p>214a. Posted Weight Limit: 090909 b. Posted Speed Limit: c. Narrow/1way Brdg Sign: d. Vertical Clr. Sign: No Adv. Warning Sign: No e. Navigation Lights?: No Working/Not Working: No</p> <p>215. Overpass: U.S. HIGHWAY 221. Substr. Cond. (U/W): 222. Fill Over RCB: 223. Appr. Slab/Rwy Cond.: 3 225. Paint Type/Ovrct: Red Lead 3 Coat System N/A</p> <p>226. Date Painted: 1933 227. Paint Color: Silver 233. Deck Forming: Conventional Forming 238. School Bus Rte.: Current & Desired route 240. Appr. Rwy Type.: Concrete 243. Grdr Spacing/No.: /</p>	<p>244. Span Lengths: 245. Girder Depth: 48.00 246a. Type of Overlay: AC Overlay b. Overlay Thickness: 3.00 c. Overlay Date: 12/04/2003 d. Ovlv Depth Changed >1": -</p> <p>247. Protective Systems: <table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td> </td><td> </td></tr> <tr><td> </td><td> </td></tr> <tr><td> </td><td> </td></tr> </table></p> <p>248. # Field Splices w/ Corrosion: 249. Scour Crit. POA Exists?: - 250. Headwall: 254. Thru Truss Type: 257a. OkiePROS Truck Routing: Yes 258. Plans w/Found. in ODOT File: 259. Scour Eval. in ODOT File: 263. Interchange at Intersection: No 264. Interstate Milepoint: -1.00</p>						

Oklahoma Dept. of Transportation - Bridge Inspection Report

NBI No.:	Structure No.:	Local ID:	Suff. Rating:								
04085	0902 0000 X	-1	21.10	SD							
PX – Corrosion and significant section loss are occurring at many locations on the lower chord, floor beams, and stringers due to deck drainage passing through joints. Widespread section loss and corrosion holes exist in the exterior stringers and end floor beams.											
152 / 1	Steel Floor Beam	ft	6,155.00	0%	0.00	62%	3,816.10	38%	2,338.90	0%	0.00
PX – Section loss with corrosion holes is common in the end floor beams and floor beams at the east truss connection (57 locations - See Appendix F). FX – Horizontal cracks in the end floor beams between the top flange and connection angle range between 5/8 inch to 9 3/16 inches (71 locations - See Appendix G)											
162 / 1	Stl Gus Plate	each	1,672.00	0%	0.00	45%	758.00	55%	914.00	0%	0.00
PX- Horizontal cracks in the inboard truss gusset plates above the bearings range in length between 6 3/4 inches to 17 5/8 inches long (10 locations - See Appendix H); Noted cracks have been strengthened; Numerous locations where paint cracks exists at this location suggesting eminent development of cracks. FX- Cracks in edge of E U4 in spans 32 and 37 due to pack rust (NEW 2018) and W U1 span 37 due to collision damage; LC inboard gusset plates typically bowed at L0 and L5 due to pack rust; West U1 span 31 has tears (1 7/8 inch and 1 inch) in edge of inboard gusset plate Bullet strike damage to E M2.5 span 4.											
205 / 1	Re Conc Column	each	78.00	0%	0.00	99%	77.00	1%	1.00	0%	0.00
FX – A 7/8-inch maximum wide crack exists in the capital of the east column of pier 3 which is emanating from the span 2 bearing anchor bolt.											
215 / 1	Re Conc Abutment	ft	49.20	50%	24.60	50%	24.60	0%	0.00	0%	0.00
No significant deficiencies were noted in the abutments except for moderate debris on the bearing seats of both abutments and map cracking exposing a few reinforcing bars at the ends of the south abutment.											
301 / 1	Pourable Joint Seal	ft	495.00	0%	0.00	0%	0.00	50%	247.50	50%	247.50
PX – Spalling of the headers was observed along the joints at piers 1, 13, 27, 33, 35 and 39; The poured joint seals typically are deteriorated and show evidence of leaking. Many of the poured seals were never installed at many of the repaired header locations leaving only the form board to fill the joint.											
310 / 1	Elastomeric Bearing	each	7.00	50%	5.00	0%	0.00	50%	2.00	0%	0.00
PX – Elastomeric bearing pads missing under beams at supplemental pier beams (beams 1-4 at pier 1, beams 1-3 at pier 39). The pads appear to be walking at pier 39 under beams 4 and 5. Unreinforced elastomeric bearing pads exists under the supplemental pier beams.											
311 / 1	Moveable Bearing	each	86.00	0%	0.00	71%	61.00	29%	25.00	0%	0.00
FX – Wear causing grooving in the expansion bearing pins and enlarging of the pin hole in the connecting gusset plates are common throughout the spans. The wear is a result of bearing rotation under live loads. This condition is most severe at L0 span 38 over pier 37 which has 3/16-inch total wear to the pin and gusset plate. Heavy pack rust with minor associated pitting is wide spread on and between the bearing components. Bronze sliding plate between the sole and masonry plates has slid out and broken at several bearings. Anchor bolts have corroded away at many of the sliding bearings.											
313 / 1	Fixed Bearing	each	84.00	0%	0.00	100%	84.00	0%	0.00	0%	0.00
Surface corrosion exists at the fixed bearings.											
330 / 1	Metal Bridge Railing	ft	7,600.00	0%	0.00	95%	7,220.00	5%	380.00	0%	0.00
FX- Pack rust is typical between the metal bridge railing, truss end posts, and web members. Small cracks were observed in the railing where the flange and web have been coped.											
859 / 1	Soffit	(EA)	1.00	0%	0.00	0%	0.00	100%	1.00	0%	0.00
FX- Spalls exposing corroded rebar are common in the underside of the deck at the expansion joints due to leakage thru joints. The underside of the deck exhibits transverse cracks with light efflorescence. Spalls and deteriorated concrete exist in exterior stringer bays at isolated locations.											
865 / 1	St.Open Gird End(5Ft)	(LF)	100.00	100%	0.00	0%	80.00	0%	20.00	0%	0.00
FX - Connection angles to pier beam 39 are deformed due to longitudinal force from approach pavement. Elastomeric bearing pads missing at supplemental pier beams (beams 1-4 at pier 1, beams 1-3 at pier 39).											
877 / 1	St. Stringer End(5Ft)	(LF)	9,501.00	0%	0.00	50%	4,750.50	50%	4,750.50	0%	0.00
PX - Significant loss including corrosion holes through exterior stringer webs at end floor beams (59 locations - See Appendix D); Cracks in the web at the top flange cope range from 1/8 inch to 2 1/2 inches long (98 locations - See Appendix A); Cracks in the stringer connection angles at the end floor beams range from 1 1/4 inches to 7 inches long (61 locations - See Appendix B); Broken rivets at the stringer connections to the end floor beams (121 rivets at 92 locations - See Appendix C).											
909 / 1	Pourable Fix Jt.Seal	(LF)	495.40	0%	0.00	0%	0.00	50%	247.70	50%	247.70
Fixed joints are paved over with transverse crack in asphalt above joint. Space between floor beams under joint at pier 20 has been filled with asphalt.											
916 / 1	St.Bearing Assembly	(LF)	4.00	100%	4.00	0%	0.00	0%	0.00	0%	0.00
Surface corrosion with no significant deficiencies. Note: Bearing assemblies do not exist between beams and supplemental pier beams											
956 / 1	St. Cracking/Fatigue	(SF)	1.00	0%	0.00	0%	0.00	100%	1.00	0%	0.00
PX- Cracks in the stringer web at the top flange cope range from 1/8 inch to 2 1/2 inches long (98 locations - See Appendix A); Cracks in the stringer connection angles at the end floor beams range from 1 1/4 inches to 7 inches long (61 locations - See Appendix B). FX- Cracks in edge of E U4 in spans 32 and 37 due to pack rust (NEW 2018) and W U1 span 37 due to collision damage; Horizontal cracks in the end floor beams between the top flange and connection angle range between 5/8 inch to 9 3/16 inches (71 locations - See Appendix G).											
957 / 1	Pack Rust Smart Flag	(EA)	1.00	0%	0.00	0%	0.00	100%	1.00	0%	0.00

Oklahoma Dept. of Transportation - Bridge Inspection Report

NBI No.:	Structure No.:	Local ID:	Suff. Rating:								
04085	0902 0000 X	-1	21.10	SD							
PX – Pack rust is common at the end post connection to the inboard gusset plate at the lower chord connection causing bowing of the gusset plates. FX – Cracks in edge of E U4 in spans 32 and 37 due to pack rust (NEW 2018); Pack rust is forming at many of the bridge railing to inboard end post channel connections. Pack rust occurs between the lower chord components and at the gusset plates at M2.5.											
961 / 1	Scour SF	(EA)	1.00	0%	0.00	0%	0.00	100%	1.00	0%	0.00
PX - Local scour exists around the columns at piers 5 through 9 and pier 23. The top of the column foundation is exposed up to 4 1/2 feet at these locations. Local scour was also observed at the columns in the flood plain north of the river.											
962 / 1	Super. Traffic Impact	(EA)	1.00	0%	0.00	0%	0.00	100%	1.00	0%	0.00
Collision damage has bent or damaged the above deck truss members with no significant loss in capacity at PX - E U3U4 span 9, W U1U2 U1L1 and the U1 gusset plate span 31, FX- W U1L2 span 6, W U1U2 and U1L2 span 37.											
963 / 1	Steel Section Loss SF	(EA)	1.00	0%	0.00	0%	0.00	100%	1.00	0%	0.00
PX - Significant loss including corrosion holes through exterior stringer webs at end floor beams (59 locations - See Appendix D); Section loss with corrosion holes is common in the end floor beams and floor beams at the east truss connection (57 locations - See Appendix F). FX- Corrosion of the lower chord has caused section loss on inboard top flange.											
965 / 1	Debris SF	(EA)	1.00	0%	0.00	100%	1.00	0%	0.00	0%	0.00
Drift consisting of large trees exists on the west flood plain under and around spans 5 through 10.											
969 / 1	OutOfPlane Dist./Load	(EA)	1.00	0%	0.00	100%	1.00	0%	0.00	0%	0.00
FX – Pier beams 1 and 39 have severe sweep and have been sistered.											
973 / 1	Horizontal Force SF	(EA)	1.00	0%	0.00	0%	0.00	100%	1.00	0%	0.00
PX- Significant approach pavement pressure occurs at both abutments pushing inward from both ends as evidenced by the movement of the deck, and sheared rivets and cracks in stringer to floor beam connections.											
975 / 1	Supplemental Support	(EA)	76.00	100%	76.00	0%	0.00	0%	0.00	0%	0.00
Shim plate between floor beam 5, span 26 and the stiff leg is rotating out from under the floor beam bottom flange.											