

REPORT OF GEOTECHNICAL INVESTIGATION

**I-35 SHOULDER SOILS SURVEY
MCCLAIN COUNTY, OKLAHOMA**

35589(04)

PROJECT NO. 22117

INTRODUCTION..... 1
 General 1
 Proposed Construction..... 1
 Scope of Work..... 1
FIELD AND LABORATORY INVESTIGATIONS 2
 Field Exploration 2
 Laboratory Testing 2
SITE DESCRIPTION..... 4
 Surface Conditions 4
 Site Geology..... 4
 Subsurface Conditions 5
 Soluble Sulfates 5
 Groundwater Conditions 6
CLOSURE..... 7

APPENDICES

- APPENDIX A – Boring Location Diagrams
- APPENDIX B – Shoulder Soils Survey Chart
- APPENDIX C – Laboratory Results
- APPENDIX D – General Notes

REPORT OF GEOTECHNICAL INVESTIGATION

I-35 SHOULDER SOILS SURVEY MCCLAIN COUNTY, OKLAHOMA

35589(04)

PROJECT NO. 22117

INTRODUCTION

General

This report presents the results of the geotechnical investigation performed for the widening of the existing pavement of I-35 in the center median and outside lanes to accommodate adding one lane of traffic in each direction from 1.0 mile south of Ladd Road extending north approximately 4.7 miles in McClain County, Oklahoma.

Proposed Construction

The project includes the widening of the existing pavement of I-35 in the center median and outside lanes to accommodate adding one lane of traffic in each direction from 1.0 mile south of Ladd Road extending north approximately 4.7 miles in McClain County, Oklahoma. The project also includes the potential overlay or reconstruction of the existing pavement of the I-35 mainline.

The purpose of this investigation is to evaluate the subsurface conditions at the site and to provide information pertaining to the geotechnical aspects of the proposed project.

Scope of Work

The scope of this investigation includes the following:

1. Review of previous geotechnical and geological information of sites near this site. This was augmented with data obtained during the field investigation phase of the project.
2. Investigation of the subsurface soils by drilling and sampling a total of 33 boreholes within the planned project area.
3. A laboratory testing program consisting of moisture content, Atterberg limits, full sieve, soluble sulfates, standard proctor and resilient modulus tests on the soils encountered
4. Presentation of laboratory test data

FIELD AND LABORATORY INVESTIGATIONS

Field Exploration

Subsurface exploration was performed from December 12th to 16th, 2022. The borings were located in the field by a representative of Red Rock Consulting by measuring distances from known site reference points as depicted on the plans provided by Olsson Associates. The locations of the borings should be considered accurate only to the degree implied by the methods used to define them.

The subsurface exploration program consisted of drilling and sampling a total of 33 borings under the full-time supervision of an engineer. All of the borings were advanced in the grass median of the existing I-35 mainline. The boring locations are shown on the Boring Location Diagrams, which are included in Appendix A.

The boring locations were drilled to depths of 36 inches beneath the existing ground surface using a HD99 Hydraulic Earth Drill. Representative samples of the borings were obtained from the auger cuttings at depths shown on the Shoulder Soils Survey chart in Appendix B.

Samples were collected and transported back to the lab for further classification and testing. The final Shoulder Soils Survey chart was developed from the draft logs, observations and test results of the samples returned to the laboratory. The stratigraphic contacts indicated are only for the specific dates and locations reported, and therefore, are not necessarily representative of other locations and times. The Shoulder Soils Survey chart, presenting conditions encountered at each location explored, are included in Appendix B.

Laboratory Testing

Representative soil samples were tested to refine the field classifications and evaluate physical properties of the soils which may affect the geotechnical aspects of project design and construction. The laboratory testing program included the following:

- Moisture content (AASHTO T265)
- Liquid limit (AASHTO T89)
- Plastic limit (AASHTO T90)
- Particle size analysis (AASHTO T88)
- Soluble sulfates (OHD L-49)
- Standard Proctor (AASHTO T99)
- Resilient modulus tests (AASHTO T307)

**I-35 Shoulder Soils Survey
McClain County, Oklahoma
35589(04)
Project No. 22117
June 23, 2023**

The results of the physical laboratory tests conducted are shown on the Shoulder Soils Survey chart in Appendix B. The laboratory results in entirety are included in Appendix C.

The above laboratory tests were performed in general accordance with applicable AASHTO procedures, or generally accepted practice. It should be noted that reference to AASHTO procedures does not imply that all cross-referenced procedures in AASHTO standards have been used, or that all AASHTO procedures used have been followed exactly. Only those AASHTO procedures and/or portions of procedures, which, in the professional judgment of the geotechnical engineer of record for this report, are applicable, appropriate, and necessary for this particular project, have been used or followed.

SITE DESCRIPTION

Surface Conditions

At the time of the field exploration, the borings were located in the existing I-35 grass median of I-35. I-35 was a four lane divided highway with a grass median for the entire length of the project. The project area was partially developed with a few businesses and a small airport near the SH 74 interchange. Continuing south along I-35 was primarily agricultural fields and a few residences. The town of Goldsby was located towards the northern end of the job.

Traffic was high on I-35 during drilling operations. Large trucks consisted of approximately half of the traffic. Traffic control was required to drill the borings.

For the Boring Location Diagrams, refer to Appendix A.

Site Geology

The geology of the project site was researched using the "Division Three Engineering Classification of Geological Materials", published by the Oklahoma Department of Transportation (ODOT) and the Geologic Map of the "Hydrologic Atlas 4 of Oklahoma," Reconnaissance of the Water Resources of the Oklahoma City quadrangle, central Oklahoma," by Roy H. Bingham and Robert L. Moore, U.S. Geological Survey, 1975.

ODOT PUBLICATION

Division Three of the "Engineering Classification of Geological Materials", published by the Oklahoma Department of Transportation (ODOT) indicates the project site consists of Terrace deposits (Qts) underlain by the Hennessey Unit (Phy).

Terrace deposits consist of sand, silt, clay, gravel, or mixtures of these. These materials were deposited by streams or wind and may be found adjacent to most streams.

The Hennessey unit consists of red platy to blocky clay shales and mudstone. The mudstones are hard and appear blocky. The red clay shale of the Hennessey unit is characterized by numerous bands or streaks of gray, white, or light green color ranging from a few inches to four feet in thickness. Small spheres of light green color up to 10 inches in diameter are an odd characteristic of the unit.

The total thickness of the unit varies from 400 to 600 feet. The Hennessey unit outcrops in a 5 to 20 mile wide north-south band across Cleveland, McClain, and Garvin Counties in Division three.

Topographically, the unit is near level to gently rolling prairies, but most of the more level outcrops of the unit are cultivated.

USGS MAP

According to the USGS geologic map, the project consists of Terrace deposits (Qt) which are underlain by Purcell Sandstone (Pp).

Terrace deposits consist of lenticular beds of sand, silt, clay, and gravel. Thickness ranges from a few feet to about 100 feet and probably averages about 50 feet along major streams. These deposits are major aquifers along Cimarron, Canadian, and North Canadian Rivers.

Purcell Sandstone consists of red-brown to maroon fine- to coarse-grained sandstone, mudstone conglomerate, and red-brown shale. Thickness, 150 feet.

Subsurface Conditions

Information collected during the field investigation indicates that the subgrade materials consisted of lean clay with various amounts of sand and silt, silty sand with various amounts of gravel, clayey sand with various amounts of gravel, sandy silt and silty, clayey sand. The subgrade materials encountered in the borings consisted of A-2-4, A-4, A-6 and A-7-6 soils. The subgrade materials encountered in the borings appeared to be native to the site except for borings SS-1, SS-5, SS-11, SS-13 and SS-17 where minor amounts of possible fill was encountered.

All of the conditions summarized above can be found on the Shoulder Soils Survey chart in Appendix B. Laboratory results can be found in Appendix C.

Soluble Sulfates

Sulfates are naturally occurring in some soils. If combined with calcium based materials, such as cement, lime, fly ash and cement kiln dust, sulfate rich soils can expand up to 250 percent of the original size when exposed to moisture.

A level of "less than 200 ppm" is the lowest and "greater than 8,000 ppm" is the highest reportable level when using the colorimeter method OHD L-49. Soluble sulfate levels less than 3,000 ppm are considered to be too low to be of concern when considering the

use of calcium based construction materials. Soluble sulfate levels in excess of 8,000 ppm are considered to be high risk.

The maximum soluble sulfate level encountered at the project site was 1,235 ppm. Since the maximum value is less than 3,000 ppm, the use of calcium based construction materials should not cause localized distresses in this project. However, good mix design and construction practices should be followed.

Any material imported to the site during construction for use as a fill material should be tested for soluble sulfates. Soluble sulfate levels are shown on the Shoulder Soils Survey chart in Appendix B and are included in Appendix C.

Groundwater Conditions

Groundwater conditions were monitored in the borings during and immediately after drilling. Groundwater was not encountered in any of the borings at these times.

To obtain more accurate groundwater level information, long-term observations in a well or piezometer that is sealed from the influence of surface water would be needed. Fluctuations in groundwater levels can occur due to seasonal variations in the amount of rainfall, runoff, altered drainage paths, and other factors not evident at the time borings were advanced. Consequently, the contractor should be aware of this possibility while constructing this project.

**I-35 Shoulder Soils Survey
McClain County, Oklahoma
35589(04)
Project No. 22117
June 23, 2023**

CLOSURE

The data presented in this report are based on the negotiated scope for this project and site conditions as they existed at the time of the field exploration. The conditions encountered in the exploratory borings are assumed to be representative of the subsurface conditions within the study area.

This report was prepared for the exclusive use of Olsson Associates, ODOT and their agents and consultants. It should be made available to prospective contractors for information and factual data only and not as a warranty of subsurface conditions similar to those interpreted from the Shoulder Soils Survey chart or discussions presented herein.

APPENDIX A

APPENDIX B

APPENDIX C

APPENDIX D

GENERAL NOTES

SOIL PROPERTY ABBREVIATIONS

N	Uncorrected SPT Penetration, blows per foot
N ₆₀	Corrected SPT Penetration, blows per foot
Q _u	Unconfined Compressive Strength, psf
Mc	Moisture Content, %
LL	Liquid Limit, %
PL	Plastic Limit, %
PI	Plasticity Index, %

DRILLING & SAMPLING ABBREVIATIONS

BS	Bag Sample
SPT	Split Spoon Sample
ST	Shelby Tube Sample
AU	Auger Sample
TC	Texas Cone Penetrometer
DCP	Dynamic Cone Penetrometer

UNIFIED SOIL CLASSIFICATION SYSTEM (ASTM D 2487)

-- used to classify all soils unless otherwise noted --

Major Divisions			Group Symbol	Typical Names
Course-Grained Soils >50% retained on #200 sieve	Gravels 50% + of course fraction retained on #4 sieve	Clean Gravels	GW	Well-graded gravels and gravel-sand mixtures, little or no fines
			GP	Poorly graded gravels and gravel-sand mixtures, little or no fines
		Gravels with Fines	GM	Silty gravels, gravel-sand-silt mixtures
			GC	Clayey gravels, gravel-sand-clay mixtures
	Sands 50% + of course fraction passes #4 sieve	Clean Sands	SW	Well-graded sands and gravelly sands, little or no fines
			SP	Poorly graded sands and gravelly sands, little or no fines
		Sands with Fines	SM	Silty sands, sand-silt mixtures
			SC	Clayey sands, sand-clay mixtures
Fine-Grained Soils <50% passes #200 sieve	Silts and Clays Liquid Limit ≤ 50%	ML	Inorganic silts, very fine sands, rock four, silty or clayey fine sands	
		CL	Inorganic clays of low to medium plasticity, gravelly/sandy/silty/lean clays	
		OL	Organic silts and organic silty clays of low plasticity	
	Silts and Clays Liquid Limit > 50%	MH	Inorganic silts, micaceous or diatomaceous fine sands or silts, elastic silts	
		CH	Inorganic clays or high plasticity, fat clays	
		OH	Organic clays of medium to high plasticity	
Highly Organic Soils			PT	Peat, muck, and other highly organic soils

Prefix: G = Gravel, S = Sand, M = Silt, C = Clay, O = Organic **Suffix:** W = Well Graded, P = Poorly Graded, M = Silty, L = Clay, LL < 50%, H = Clay, LL > 50%

PLASTICITY OF COHESIVE SOIL

Degree of Plasticity	Plasticity Index	Swell Potential
None	0 to 4	Very Low
Slight	5 to 9	Low
Medium	10 to 19	Low to Medium
High	20 to 39	Medium to High
Very High	40+	Very High

CONSISTENCY - COHESIVE SOILS

Consistency	SPT
Very Soft	<2
Soft	2 to 4
Medium Stiff	5 to 8
Stiff	9 to 14
Very Stiff	15 to 30
Hard	31+

ROCK HARDNESS

SPT (in/50)	TCP (in/100)	Rock Description
6+	6+	Very Soft / Very Poorly Cemented
5 - 6	3 - 6	Soft / Poorly Cemented
4 - 5	2 - 3	Moderately Hard / Cemented
3 - 4	1 - 2	Hard / Well Cemented
<3	<1	Very Hard / Very Well Cemented

MOISTURE OF COHESIVE SOIL

Description	Condition	Moisture Content
Dry, Dusty	Dry	0 to 10%
Damp	Moist	10 to 30%
Free Water	Wet	30 to 70%

DENSITY - COHESIONLESS SOILS

Relative Density	SPT
Very Loose	<4
Loose	4 to 10
Medium Dense	11 to 30
Dense	31 to 50
Very Dense	51+

ROCK CORE QUALITY

Core Quality	RQD
Excellent Quality	90 - 100%
Good Quality	75 - 90%
Fair Quality	50 - 75%
Poor Quality	25 - 50%
Very Poor Quality	<25%