OKLAHOMA DEPARTMENT OF ENVIRONMENTAL QUALITY



Hydrochloric Acid or Sulfuric Acid Spills from Trucks or Tank Cars

This is to provide guidance for cleanup of hydrochloric acid (HCl) or sulfuric acid (H2SO4) from truck or tank car spills. These chemicals correspond to Chemical Abstracts Service (CAS) Numbers 7647-01-0 and 7664-93-9, respectively. Spills of hydrochloric acid or sulfuric acid can lead to significant contamination of the environment if not addressed quickly and properly. The Oklahoma Department of Environmental Quality's (DEQ's) goal is to have spills cleaned up within 72 hours of an incident. Spills should be reported to DEQ's 24-hour hotline at (800) 522-0206. If reportable quantities (RQs) are exceeded, then other agencies will need to be notified as well.

Spills resulting from a motor vehicle collision on any public roadway must be cleaned up by a remediation contractor licensed by DEQ's Environmental Complaints and Local Services Division (ECLS). A list of these contractors can be found at https://tinyurl.com/y6ja4fbx. The immediate objective is to neutralize and recover free liquids to prevent them from contaminating surface water or ground water. Appropriate action, such as using booms and dikes, must be taken to keep free liquids from reaching surface water. Once free liquids are addressed, excavation of contaminated soil will be necessary. Contaminated soil needs to be removed because contaminants can leach into groundwater or spread to surface water if there is rain.

If contaminated soil extends into groundwater or groundwater contamination is otherwise suspected, contact DEQ's Voluntary Cleanup Program (VCP) for assistance at (405) 702-5100. If public water supplies are threatened or surface water is impacted, notify DEQ's Water Quality Division at (405) 702-8100.

Soil Excavation

For removal of contaminated soil, the standard practice is to excavate visible contamination, screen the excavation site for hot spots using pH strips as an indicator of contamination, then take confirmation samples to show that the contaminated soil has been removed.

Contaminated soil should be temporarily containerized or stockpiled on plastic sheeting, minimum 10 mil, covered and bermed to prevent run-on and run-off. If an open pit must be backfilled due to extenuating circumstances, the floor of the excavation should be covered with plastic sheeting or some other suitable method to clearly define the sidewalls and bottom of the pit in the event test results show the need for further excavation.

Confirmation Samples and Analysis

Confirmation sampling is done to determine if cleanup has been adequate. The number of samples to be collected depends on the size of the release and where it occurred. Additional samples may be required for further delineation.

Excavations of 400 square feet or less. A minimum of five grab samples must be taken –
one from each side wall and one from the bottom of the excavation for every 400 square
feet of excavated area.



This publication is issued by the Oklahoma Department of Environmental Quality authorized by Rob Singletary, Executive Director. Copies have been prepared at a cost of \$0.212 each. Copies have been deposited with the publications clearinghouse of the Oklahoma Department of Libraries. (Fact Sheets\LPD\Highway Acid Spills. indd 11/2025)

Hydrochloric Acid or Sulfuric Acid Spills



- Excavations exceeding 400 square feet. Confirmation sampling consists of one grab sample every 20 linear feet around the perimeter sidewalls and one from the bottom of the excavation for every 400 square feet of excavation area.
- Releases to a ditch. Grab samples should be taken every 20 feet and analyzed separately.
- Acid spills. In addition to the above, acid spills must be analyzed for total soluble salts and the
 applicable anion.
 - Soil samples should be placed in suitable, acid-resistant containers, with chain-of-custody records completed, and sent to a certified lab.
 - Analyses should include salinity parameters for pH, total soluble salts, chloride for hydrochloric acid spills, and sulfate for sulfuric acid spills (for example, OSU's Comprehensive Salinity package).

Acceptable cleanup levels for soil are:

Total soluble salts	<2,640 mg/kg
Chloride	<1,000 mg/kg
Sulfate	<1,000 mg/kg

Depending on site-specific conditions and response time, surface samples may be all that is needed; however, soil samples should be taken at one-foot depth intervals to a depth of at least three feet (grab samples at 0 to 1 feet, 1 to 2 feet, and 2 to 3 feet below excavated surface) if:

- more than one week has passed since the spill;
- a significant rainfall event has occurred; or
- if plowed or sandy soil is present.

If significant time has elapsed before cleanup is completed, testing the groundwater may be required.

Acceptable cleanup levels for acid spill impacted groundwater are:

Total soluble salts	<500 mg/l
Chloride	<250 mg/l
Sulfate	<250 mg/l

For certain sites, background levels may exceed the cleanup levels listed above; in this case, documented background samples from media unaffected by a spill must be taken to demonstrate adequate cleanup to background levels.

Final Report

The responsible party should consult with DEQ to verify that the planned sampling adequately addresses the release. The responsible party should submit a final report to the DEQ ECLS Division documenting material spilled and actions taken. The report should also include analytical data to demonstrate that cleanup levels were achieved.

Spills of Materials Other Than Hydrochloric Acid or Sulfuric Acid

Spills other than hydrochloric acid or sulfuric acid need to be addressed on a case-by-case basis. If reportable quantities (RQs) are exceeded contact the National Response Center at (800) 424-8802. Other reporting requirements may be necessary. Contact DEQ's 24-hour hotline at (800) 522-0206 for assistance with reporting requirements.

Hydrochloric Acid or Sulfuric Acid Spills



References

Oklahoma Corporation Commission, July 2014, Pollution Abatement Department, Oil and Gas Conservation Division, Guardian Guidance for the Assessment and Cleanup of Complex Crude Oil, Condensate, and Other Hydrocarbon Release Sites, Including Historically Impacted Sites.

https://tinyurl.com/vjtpaaky

Kansas Corporation Commission, Conservation Division, Clean up Guidelines for: Spills and Escapes https://www.kcc.ks.gov/oil-gas/clean-up-guidelines

Spill Guidance Procedural Checklist

Contact information including name, phone and address of carrier, emergency response contractor, and insurance company:

	Yes	No			
1. Have liquids been contained and recovered?			If not, do so.		
2. What was spilled?	How much? gallons				
3. Has contamination reached surface water?			If yes, boom and vac. Contact DEQ's WQD at (405) 702-8100.		
4. Have appropriate spill notifications been made? DEQ 24-hour hotline (800) 522-0206 National Response Center (800) 424-8802					
5. Is there surface water nearby?			If yes, how close?		
6. Are there public water supply wells or water supply lines nearby?			If yes, contact the affected municipality and DEQ's WQD.		
7. If water supply lines are nearby, what are they made of?					
8. Is the spill in a wellhead protection area?					
9. Are there private wells nearby?			If yes, what are the wells used for?		
10. Are any utilities affected?					
11. Has contamination gotten into sewer lines?					
12. Has visibly contaminated soil been excavated?			Field screen with pH strips if possible.		
13. Was groundwater encountered during excavation?					
14. Does contamination extend down to groundwater or is groundwater contamination otherwise suspected?			If yes, contact DEQ's VCP at (405) 702-5100.		
15. Has contaminated soil been properly stockpiled or disposed?					
16. Has there been appropriate confirmation sampling?					
17. Were samples analyzed by correct methods?					
18. Do confirmation samples meet cleanup levels?			If not, dig more or contact DEQ's VCP.		
Draw site map, noting relevant features, stockpile locations and similar items.					