OKLAHOMA DRINKING WATER
LEAD TESTING
IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Washington Pre Kg Center
Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma Lead in Schools and Child Care Program (LWSC) on 10/01/2026 from 1615 N 7Th, Ponca City, OK 74601.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:
CF: Classroom Faucet
KF: Kitchen Faucet
BF: Bathroom Faucet
NS: Nurse Office Sink
RA: Refrigerator Appliance
OF: Outdoor Faucet
IM: Ice Machine
DW: Drinking Water Fountain
WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	3805-1	1	1	Room 5	DW		Bubbler to the right of the sink	2.05 ppb	1.02 ppb	10/02/2026 06:30	Remediation Recommended	
2	3805-15	1	1	Room 2	DW		Water fountain	1.93 ppb	<1 ppb	10/01/2026 06:30	Remediation Recommended	
3	3805-14	1	1	Room 3	DW		Water fountain	1.04 ppb	<1 ppb	10/01/2026 06:30	Remediation Recommended	
4	3805-11	1	1	Across the Gym entrance	WC	Elkay	Water fountain to the right in the hallway	<1 ppb	1.03 ppb	10/01/2026 06:30	Remediation Recommended	
5	3805-2	1	1	Room 6	DW		Bubbler to the right of the sink	<1 ppb	<1 ppb	10/02/2026 06:30	No Further Action	
6	3805-3	1	1	Room 7	DW		Bubbler to the right of the sink	<1 ppb	<1 ppb	10/02/2026 06:30	No Further Action	
7	3805-4	1	1	Room 8	DW		Bubbler to the right of the sink	<1 ppb	<1 ppb	10/02/2026 06:30	No Further Action	
8	3805-5	1	1	Across Room 9	WC	Elkay	Water fountain in the hallway	<1 ppb	<1 ppb	10/02/2026 06:30	No Further Action	
9	3805-6	1	1	Room 9	DW		Bubbler to the right of the sink	<1 ppb	<1 ppb	10/02/2026 06:30	No Further Action	
10	3805-7	1	1	Room 13	DW		Bubbler to the right of the sink	<1 ppb	<1 ppb	10/02/2026 06:30	No Further Action	
11	3805-8	1	1	Room 12	DW		Bubbler to the right of the sink	<1 ppb	<1 ppb	10/02/2026 06:30	No Further Action	
12	3805-9	1	1	Room 11	DW		Bubbler to the right of the sink	<1 ppb	<1 ppb	10/02/2026 06:30	No Further Action	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
13	3805-10	1	1	Across the Gym entrance	WC	Elkay	Water fountain to the left in the hallway	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
14	3805-12	1	1	Main office	CF		Sink in the main office	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
15	3805-13	1	1	Room 1	DW		Water fountain	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	