OKLAHOMA DRINKING WATER
LEAD TESTING
IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Roosevelt Es
Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma Lead in Schools and Child Care Program (LWSC) on 10/01/2026 from 815 East Highland Avenue, Ponca City, OK 74601.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:
CF: Classroom Faucet
KF: Kitchen Faucet
BF: Bathroom Faucet
NS: Nurse Office Sink
RA: Refrigerator Appliance
OF: Outdoor Faucet
IM: Ice Machine
DW: Drinking Water Fountain
WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	3809-11	2	1	Room 3a	WC	Elkay	Water Fountain	<1 ppb	6.71 ppb	10/01/2026 06:30	Remediation Recommended	
2	3809-10	2	1	Room 4a	WC	Elkay	Water Fountain	<1 ppb	1.14 ppb	10/01/2026 06:30	Remediation Recommended	
3	3809-1	1	1	Cafeteria	WC	Elkay ezH2O	Left Side, Water fountain	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
4	3809-2	1	1	Cafeteria	WC	Elkay ezH2O	Right Side, Water fountain	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
5	3809-3	1	2	Behind the gym	WC	Elkay ezH2O	Left Side, Water fountain	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
6	3809-4	1	2	Behind the gym	WC	Elkay ezH2O	Right Side, Water fountain	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
7	3809-5	1	2	To the Right of Room 110	WC	Elkay ezH2O	Left Side, Water fountain	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
8	3809-6	1	2	To the Right of Room 110	WC	Elkay ezH2O	Right Side, Water fountain	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
9	3809-7	1	1	To the Right of Room 106	WC	Elkay ezH2O	Left Side, Water fountain	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
10	3809-8	1	1	To the Right of Room 106	WC	Elkay ezH2O	Right Side, Water fountain	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
11	3809-9	1	1	Main Office	IM		IM	<1 ppb		10/01/2026 06:30	No Further Action	
12	3809-12	2	1	Room 2a	CF		Sink	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
13	3809-13	2	1	Room 1a	CF		Sink	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
14	3809-14	3	1	Across Room 3	WC	Elkay ezH2O	Bottle Filler	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
15	3809-15	3	1	Across Room 3	WC	Elkay ezH2O	Water Fountain	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
16	3809-16	3	1	In Room 6	CF		Sink	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
17	3809-17	3	1	To the right of Room 2	WC	Elkay	Water Fountain, Left Side	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	
18	3809-18	3	1	To the right of Room 2	WC	Elkay	Water Fountain, Right Side	<1 ppb	<1 ppb	10/01/2026 06:30	No Further Action	