OKLAHOMA DRINKING WATER
LEAD TESTING
IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

# Ponca City West Ms
# Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma Lead in Schools and Child Care Program (LWSC) on 09/30/2026 from 1401 West Grand Avenue, Ponca City, OK 74601.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:
CF: Classroom Faucet
KF: Kitchen Faucet
BF: Bathroom Faucet
NS: Nurse Office Sink
RA: Refrigerator Appliance
OF: Outdoor Faucet
IM: Ice Machine
DW: Drinking Water Fountain
WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

| # | Outlet ID | Building # | Floor # | Room # / Name | Outlet Type Code | Water Cooler Make and Model | Comments | Initial First Draw Result Final (ppb) | Initial Flush Draw Result Final (ppb) | Initial Sample Date(s) | Action Needed? | Remediation Action Taken |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 3813-22 | 1 | 1 | Cafeteria | WC | Elkay | Water Fountain | 1.6 ppb | 15 ppb | 9/30/26 5:30 | Remediation Strongly Suggested | |
| 2 | 3813-13 | 1 | 1 | Room 113 - Food Lab | CF | | Classroom – right wall, first sink immediately inside entry | 3.3 ppb | <1 ppb | 9/30/26 5:30 | Remediation Recommended | |
| 3 | 3813-19 | 1 | 1 | Room 113 - Food Lab | CF | | Classroom – left wall, first sink from entry | 1.9 ppb | <1 ppb | 9/30/26 5:30 | Remediation Recommended | |
| 4 | 3813-14 | 1 | 1 | Room 113 - Food Lab | CF | | Classroom – right wall, second sink | 1.7 ppb | <1 ppb | 9/30/26 5:30 | Remediation Recommended | |
| 5 | 3813-15 | 1 | 1 | Room 113 - Food Lab | CF | | Classroom – left wall, second sink from entry | 1.2 ppb | <1 ppb | 9/30/26 5:30 | Remediation Recommended | |
| 6 | 3813-18 | 1 | 1 | Room 113 - Food Lab | CF | | Classroom – left wall, fifth sink from entry, nearest front of room | 1.2 ppb | 1.1 ppb | 9/30/26 5:30 | Remediation Recommended | |
| 7 | 3813-1 | 1 | 1 | Kitchen | KF | | Cooking (steam) Kettles - front side | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 8 | 3813-2 | 1 | 1 | Kitchen | KF | | Cooking (steam) Kettles - back side | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 9 | 3813-3 | 1 | 1 | Kitchen | KF | | Sink in the cooking area | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 10 | 3813-4 | 1 | 1 | Kitchen | IM | Ice-O-Matic | IM | <1 ppb | | 9/30/26 5:30 | No Further Action | |

| # | Outlet ID | Building # | Floor # | Room # / Name | Outlet Type Code | Water Cooler Make and Model | Comments | Initial First Draw Result Final (ppb) | Initial Flush Draw Result Final (ppb) | Initial Sample Date(s) | Action Needed? | Remediation Action Taken |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 11 | 3813-5 | 1 | 1 | Kitchen | KF | | Sink in the cutting area - right side | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 12 | 3813-6 | 1 | 1 | Kitchen | KF | | Sink in the cutting area - left side | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 13 | 3813-7 | 1 | 1 | Across Room 130 | WC | Elkay | Left side, Water fountain | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 14 | 3813-8 | 1 | 1 | Across Room 130 | WC | Elkay | Right side, Water fountain | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 15 | 3813-9 | 1 | 1 | Across Room 150 | WC | Elkay | Water Fountain | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 16 | 3813-10 | 1 | 1 | Gym | WC | Elkay | Girl's Locker | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 17 | 3813-11 | 1 | 1 | Left to Room 113 - Food Lab | WC | Elkay - ezH2O | Bottle filler | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 18 | 3813-12 | 1 | 1 | Left to Room 113 - Food Lab | WC | Elkay - ezH2O | Water fountain | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 19 | 3813-16 | 1 | 1 | Room 113 - Food Lab | CF | | Classroom – left wall, third sink from entry | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 20 | 3813-17 | 1 | 1 | Room 113 - Food Lab | CF | | Classroom – left wall, fourth sink from entry | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 21 | 3813-20 | 1 | 1 | Teacher's Lounge | IM | Manitowoc | IM | <1 ppb | | 9/30/26 5:30 | No Further Action | |
| 22 | 3813-21 | 1 | 1 | To the right of Room 109 | WC | Elkay | Water Fountain | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 23 | 3813-23 | 1 | 2 | Across Room 201 | WC | Elkay - ezH2O | Water Fountain | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |

| # | Outlet ID | Building # | Floor # | Room # / Name | Outlet Type Code | Water Cooler Make and Model | Comments | Initial First Draw Result Final (ppb) | Initial Flush Draw Result Final (ppb) | Initial Sample Date(s) | Action Needed? | Remediation Action Taken |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 24 | 3813-24 | 1 | 2 | Across Room 201 | WC | Elkay - ezH2O | Bottle Filler | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 25 | 3813-25 | 1 | 2 | Across Room 209 | WC | Elkay - ezH2O | Water Fountain | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 26 | 3813-26 | 1 | 2 | Across Room 209 | WC | Elkay - ezH2O | Bottle Filler | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 27 | 3813-27 | 1 | 2 | Between Rooms 216 and 217 | WC | Elkay - ezH2O | Bottle Filler | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| 28 | 3813-28 | 1 | 2 | Between Rooms 216 and 217 | WC | Elkay - ezH2O | Water Fountain | <1 ppb | <1 ppb | 9/30/26 5:30 | No Further Action | |
| | | | | | | | | | | | | |