OKLAHOMA DRINKING WATER
LEAD TESTING
IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Ponca City East Ms
Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma Lead in Schools and Child Care Program (LWSC) on 09/29/2026 from 612 East Grand, Ponca City, OK 74601.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:
CF: Classroom Faucet
KF: Kitchen Faucet
BF: Bathroom Faucet
NS: Nurse Office Sink
RA: Refrigerator Appliance
OF: Outdoor Faucet
IM: Ice Machine
DW: Drinking Water Fountain
WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	3814-4	1	1	Across Room 146 - IT Classroom	WC	Elkay	Right side, water fountain	<1 ppb	2 ppb	9/29/26 5:30	Remediation Recommended	
2	3814-10	1	2	Room 220 - Home Economics	CF		Extreme left side sink; to the left wall	1.4 ppb	<1 ppb	9/29/26 5:30	Remediation Recommended	
3	3814-1	1	1	To the right when we enter	WC	Elkay	Left side, water fountain	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	
4	3814-2	1	1	To the right when we enter	WC	Elkay	Right side, water fountain	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	
5	3814-3	1	1	Across Room 146 - IT Classroom	WC	Elkay	Left side, water fountain	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	
6	3814-5	1	1	To the left of the kitchen	WC	Elkay	Left side, water fountain	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	
7	3814-6	1	1	To the left of the kitchen	WC	Elkay	Right side, water fountain	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	
8	3814-7	1	1	To the left of the kitchen	WC	Elkay	Right side, bottle filler	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	
9	3814-8	1	1	Kitchen	IM		IM to the right of the sink	<1 ppb		9/29/26 5:30	No Further Action	
10	3814-9	1	1	Kitchen	KF		Sink	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	
11	3814-11	1	2	Room 220 - Home Economics	CF		Middle sink in the classroom; to the left wall	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	
12	3814-12	1	2	Room 220 - Home Economics	CF		Extreme right side sink; to the left wall	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
13	3814-13	1	2	Room 220 - Home Economics	CF		Left side sink to the front wall	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	
14	3814-14	1	2	Room 220 - Home Economics	CF		Right side sink to the front wall	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	
15	3814-15	1	2	Room 220 - Home Economics	RA	Frigidaire	IM	<1 ppb		9/29/26 5:30	No Further Action	
16	3814-16	1	2	To the left of Room 220	WC	Elkay	Left side, water fountain	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	
17	3814-17	1	2	To the left of Room 220	WC	Elkay	Right side, water fountain	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	
18	3814-18	1	2	To the left of Room 204	WC	Elkay	Left side, water fountain	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	
19	3814-19	1	2	To the left of Room 204	WC	Elkay	Right side, water fountain	<1 ppb	<1 ppb	9/29/26 5:30	No Further Action	