OKLAHOMA DRINKING WATER
# LEAD TESTING
IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

# Ridgecrest Es
# Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma Lead in Schools and Child Care Program (LWSC) on 10/09/2026 from 137 W Ridgewood Drive, Midwest City, OK 73110.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:
CF: Classroom Faucet
KF: Kitchen Faucet
BF: Bathroom Faucet
NS: Nurse Office Sink
RA: Refrigerator Appliance
OF: Outdoor Faucet
IM: Ice Machine
DW: Drinking Water Fountain
WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

| # | Outlet ID | Building # | Floor # | Room # / Name | Outlet Type Code | Water Cooler Make and Model | Comments | Initial First Draw Result Final (ppb) | Initial Flush Draw Result Final (ppb) | Initial Sample Date(s) | Action Needed? | Remediation Action Taken |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 4217-4 | 1 | 1 | Kitchen | KF | | Sink on the right when we enter | 2.88 ppb | <1 ppb | 10/09/2026 06:00 | Remediation Recommended | |
| 2 | 4217-16 | 1 | 1 | Library work room (20 B) | KF | | Sink in the back | 2.62 ppb | <1 ppb | 10/09/2026 06:00 | Remediation Recommended | |
| 3 | 4217-5 | 1 | 1 | Kitchen | KF | | Sink to the left when we enter | 2.45 ppb | <1 ppb | 10/09/2026 06:00 | Remediation Recommended | |
| 4 | 4217-15 | 1 | 1 | Library | WC | Elkay | WF at the library entrance | 2.04 ppb | 1.87 ppb | 10/09/2026 06:00 | Remediation Recommended | |
| 5 | 4217-14 | 1 | 1 | Across Room 16 | WC | Elkay | WF to the right | 1.33 ppb | <1 ppb | 10/09/2026 06:00 | Remediation Recommended | |
| 6 | 4217-1 | 1 | 1 | Main entrance hallway - next to the office | WC | Elkay | WF to the left | 1.08 ppb | <1 ppb | 10/09/2026 06:00 | Remediation Recommended | |
| 7 | 4217-8 | 1 | 1 | Hallway- Next to work room | WC | Elkay | WF to the right | 1.04 ppb | <1 ppb | 10/09/2026 06:00 | Remediation Recommended | |
| 8 | 4217-3 | 1 | 1 | Main entrance hallway - next to the office | WC | Elkay | WF to the right | <1 ppb | <1 ppb | 10/09/2026 06:00 | No Further Action | |
| 9 | 4217-2 | 1 | 1 | Main entrance hallway - next to the office | WC | Elkay | BF to the right | <1 ppb | <1 ppb | 10/09/2026 06:00 | No Further Action | |
| 10 | 4217-6 | 1 | 1 | Hallway- Next to work room | WC | Elkay | WF to the left | <1 ppb | <1 ppb | 10/09/2026 06:00 | No Further Action | |
| 11 | 4217-10 | 1 | 1 | Across Room 4 | WC | Elkay | BF to the right | <1 ppb | <1 ppb | 10/09/2026 06:00 | No Further Action | |

| # | Outlet ID | Building # | Floor # | Room # / Name | Outlet Type Code | Water Cooler Make and Model | Comments | Initial First Draw Result Final (ppb) | Initial Flush Draw Result Final (ppb) | Initial Sample Date(s) | Action Needed? | Remediation Action Taken |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 12 | 4217-9 | 1 | 1 | Across Room 4 | WC | Elkay | WF to the left | <1 ppb | <1 ppb | 10/09/2026 06:00 | No Further Action | |
| 13 | 4217-7 | 1 | 1 | Hallway- Next to work room | WC | Elkay | BF to the right | <1 ppb | <1 ppb | 10/09/2026 06:00 | No Further Action | |
| 14 | 4217-13 | 1 | 1 | Across Room 16 | WC | Elkay | BF to the right | <1 ppb | <1 ppb | 10/09/2026 06:00 | No Further Action | |
| 15 | 4217-11 | 1 | 1 | Across Room 4 | WC | Elkay | WF to the right | <1 ppb | <1 ppb | 10/09/2026 06:00 | No Further Action | |
| 16 | 4217-12 | 1 | 1 | Across Room 16 | WC | Elkay | WF to the left | <1 ppb | <1 ppb | 10/09/2026 06:00 | No Further Action | |
| | | | | | | | | | | | | |