



OKLAHOMA DRINKING WATER

LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Sunbeam Early Education Center Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma Lead in Schools and Child Care Program (LWSC) on 08/13/2026 from 1100 Nw 14Th Building B, Oklahoma City, OK 73106.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:

CF: Classroom Faucet

KF: Kitchen Faucet

BF: Bathroom Faucet

NS: Nurse Office Sink

RA: Refrigerator Appliance

OF: Outdoor Faucet

IM: Ice Machine

DW: Drinking Water Fountain

WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	5327-14	1	1	Classroom 118	CF		To the right	4.69 ppb	<1 ppb	08/13/2026 06:30	Remediation Recommended	
2	5327-7	1	1	Classroom 120	CF		In the center	4.13 ppb	<1 ppb	08/13/2026 06:30	Remediation Recommended	
3	5327-13	1	1	Classroom 115	BF			3.58 ppb	<1 ppb	08/13/2026 06:30	Remediation Recommended	
4	5327-21	1	1	Staff Room 104	RA	Scotsman	To the left corner	3.2 ppb	<1 ppb	08/13/2026 06:30	Remediation Recommended	
5	5327-15	1	1	Classroom 118	CF		In the center	2.15 ppb	<1 ppb	08/13/2026 06:30	Remediation Recommended	
6	5327-16	1	1	Classroom 118	CF		To the left	1.97 ppb	<1 ppb	08/13/2026 06:30	Remediation Recommended	
7	5327-6	1	1	Classroom 120	CF		To the right	1.92 ppb	<1 ppb	08/13/2026 06:30	Remediation Recommended	
8	5327-8	1	1	Classroom 120	CF		To the left	1.29 ppb	<1 ppb	08/13/2026 06:30	Remediation Recommended	
9	5327-1	1	1	Classroom 110	CF		Gross Motor Room	1.02 ppb	<1 ppb	08/13/2026 06:30	Remediation Recommended	
10	5327-2	1	1	109	KF		Kitchen	<1 ppb	<1 ppb	08/13/2026 06:30	No Further Action	
11	5327-3	1	1	Next to room 113	WC	Elkay ezH2O	Filter status orange; Right one	<1 ppb	<1 ppb	08/13/2026 06:30	No Further Action	
12	5327-4	1	1	Next to room 113	WC	Elkay ezH2O	Left one	<1 ppb	<1 ppb	08/13/2026 06:30	No Further Action	
13	5327-5	1	1	Next to room 113	WC	Elkay ezH2O	Right one	<1 ppb	<1 ppb	08/13/2026 06:30	No Further Action	
14	5327-9	1	1	Classroom 115	CF		To the right	<1 ppb	<1 ppb	08/13/2026 06:30	No Further Action	
15	5327-10	1	1	Classroom 115	CF		In the center	<1 ppb	<1 ppb	08/13/2026 06:30	No Further Action	
16	5327-11	1	1	Classroom 115	CF		To the left	<1 ppb	<1 ppb	08/13/2026 06:30	No Further Action	

#	Outlet ID	Buildin g #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
17	5327-12	1	1	Classroom 117	BF			<1 ppb	<1 ppb	08/13/2026 06:30	No Further Action	
18	5327-18	1	1	Classroom 117	CF		In the center	<1 ppb	<1 ppb	08/13/2026 06:30	No Further Action	
19	5327-17	1	1	Classroom 117	CF		To the Left	<1 ppb	<1 ppb	08/13/2026 06:30	No Further Action	
20	5327-19	1	1	Classroom 117	CF		To the right	<1 ppb	<1 ppb	08/13/2026 06:30	No Further Action	
21	5327-20	1	1	Staff Room 104	CF		Right Sink	<1 ppb	<1 ppb	08/13/2026 06:30	No Further Action	