



**STATE OF OKLAHOMA
BOARD OF TESTS FOR ALCOHOL AND DRUG INFLUENCE**

Dr. Jarrad Wagner, Ph.D., F-ABFT
Chairman

Post Office Box 36307
Oklahoma City, Oklahoma 73136-2307
Phone: (405) 425-2460 Fax: (405) 425-2490
www.bot.ok.gov

Joshua Smith
Director

03/17/2026

MEMORANDUM

****NOTICE TO IDAP PARTICIPANTS REGARDING INTOXALOCK® IGNITION INTERLOCK SERVICE DISRUPTION****

The Oklahoma Board of Tests for Alcohol and Drug Influence (“Board”) has received reports of nationwide service disruptions affecting certain ignition interlock devices and related systems associated with Intoxalock®.

The Board does not operate, control, or maintain ignition interlock devices or vendor systems. At this time, as authorized agent of the Board pursuant to law, I hereby issue the following instructions and notice. All IDAP participants shall remain subject to applicable laws, rules, and individual program requirements.

Participants who experience device or service issues are responsible for taking reasonable steps to address the situation, including:

1. ****Promptly contacting the vendor**** to report the issue and request service;
2. ****Documenting all relevant circumstances****, including dates, times, device messages, and communications;
3. ****Retaining records of all service attempts and outcomes****

Nothing in this notice alters, expands, or limits any participant’s legal obligations for other ignition interlock devices or vendors. The determination of compliance, including the evaluation of any reported device or service issue, will be made by Board of Tests based on the totality of the circumstances and applicable law.

The Board is monitoring available information regarding reported service disruptions. This notice is informational only and does not constitute legal advice or a determination regarding any individual participant’s compliance status.

****This notice may be updated or withdrawn without prior notice.****

Joshua Smith
State Director of Tests