



## RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at Sunbeam Family Services - Gatewood Early Learning Center on October 10, 2024. Overall, seven (7) outlets were tested resulting in a total of fourteen (14) samples being sent to the lab.

- Fourteen (14) samples had no detectable level of lead.
- Zero (0) samples had a low detection of lead between 1.0 and 14.9 µg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 µg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as µg/L. For more information on how to read this report, please see our **Results Interpretation Fact Sheet**.

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
<b>Non-Detect (&lt;1.0 µg/L)</b>				
1-1-319-CF1	Classroom faucet in Rm 319	<1.0	<1.0	N/A
1-1-GH-WC1	Elkay bottle filler in gym hall; left side	<1.0	<1.0	N/A
1-1-GH-WC2	Elkay water cooler with bottle filler in gym hall; left side	<1.0	<1.0	N/A
1-1-GH-WC3	Elkay bottle filler in gym hall; right side	<1.0	<1.0	N/A
1-1-GH-WC4	Elkay water cooler with bottle filler in gym hall; right side	<1.0	<1.0	N/A
1-2-KIT-KF1	Kitchen faucet in facility kitchen	<1.0	<1.0	N/A
1-1-319-CF2	Classroom faucet in Rm 319; short sink	<1.0	<1.0	N/A