

District: Southwest Oklahoma Community Action Group

School: <u>Hollis Head Start</u> Sampling Date: <u>10/24/2024</u>

Status: Remediation

RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at Southwest Oklahoma Community Action Group - Hollis Head Start on October 24, 2024. Overall, four (4) outlets were tested resulting in a total of eight (8) samples being sent to the lab.

- Six (6) samples had no detectable level of lead.
- Two (2) samples had a low detection of lead between 1.0 and 14.9 μ g/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 μg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as $\mu g/L$. For more information on how to read this report, please see our **Results Interpretation** Fact Sheet.

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
Non-Detect (<1.0 μg/L)				
1-1-KIT-KF2	Kitchen faucet in facility kitchen; 3-bay sink	<1.0	<1.0	N/A
1-1-2B-BF1	Bathroom faucet in Rm 2 bathroom	<1.0	<1.0	N/A
Low Detection (1.0 - 14.9 μg/L)				
1-1-3-BF1	Bathroom faucet in Rm 3	1.5	<1.0	
1-1-KIT-KF1	Kitchen faucet in facility kitchen; near entrance	1.8	<1.0	