



OKLAHOMA DRINKING WATER

LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Cn Children'S Village Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma Lead in Schools and Child Care Program (LWSC) on 06/16/2026 from 22675 Betty Sharp Smith St, Tahlequah, OK 74464.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:

CF: Classroom Faucet

KF: Kitchen Faucet

BF: Bathroom Faucet

NS: Nurse Office Sink

RA: Refrigerator Appliance

OF: Outdoor Faucet

IM: Ice Machine

DW: Drinking Water Fountain

WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	2087-4	1	1	Across from 123	WC	OASIS	Left bottle filler	128 ppb	3.36 ppb	6/16/2026 7:00:00 AM	Remediation Strongly Suggested	
2	2087-37	1	2	255	CF		Front of classroom, right of fridge	54.7 ppb	60.3 ppb	6/16/2026 7:52:00 AM	Remediation Strongly Suggested	
3	2087-6	1	1	Across from 123	WC	OASIS	Right fountain	53.1 ppb	38.4 ppb	6/16/2026 7:00:00 AM	Remediation Strongly Suggested	
4	2087-39	1	2	259	CF		Front of classroom, left of fridge	1.72 ppb	16.8 ppb	6/16/2026 7:52:00 AM	Remediation Strongly Suggested	
5	2087-5	1	1	Across from 123	WC	OASIS	Left fountain	5.49 ppb	2.64 ppb	6/16/2026 7:00:00 AM	Remediation Recommended	
6	2087-24	1	2	Kitchen	KF		Pot filler, left of freezer	5.48 ppb	<1 ppb	6/16/2026 7:38:00 AM	Remediation Recommended	
7	2087-38	1	2	257	CF		Front of classroom, left of fridge	4.94 ppb	3.71 ppb	6/16/2026 7:52:00 AM	Remediation Recommended	
8	2087-7	1	1	146	CF		Small faucet	4.04 ppb	<1 ppb	6/16/2026 7:00:00 AM	Remediation Recommended	
9	2087-13	1	1	110	CF		Back of classroom	2.47 ppb	1.54 ppb	6/16/2026 7:15:00 AM	Remediation Recommended	
10	2087-23	1	2	Kitchen	KF		Pot filler, right of oven	1.73 ppb	<1 ppb	6/16/2026 7:38:00 AM	Remediation Recommended	
11	2087-36	1	2	254	CF		Front of classroom, left of fridge	1.53 ppb	<1 ppb	6/16/2026 7:52:00 AM	Remediation Recommended	
12	2087-35	1	2	252	CF		Front of classroom, right of fridge	1.17 ppb	1.13 ppb	6/16/2026 7:52:00 AM	Remediation Recommended	
13	2087-21	1	2	Kitchen	KF		Right side of kitchen, 2 compartment	1.14 ppb	<1 ppb	6/16/2026 7:15:00 AM	Remediation Recommended	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
14	2087-30	1	2	206	CF		Front of classroom, right of fridge	<1 ppb	1.09 ppb	6/16/2026 7:38:00 AM	Remediation Recommended	
15	2087-17	1	1	106	CF		Front of classroom, left of fridge	1.02 ppb	<1 ppb	6/16/2026 7:15:00 AM	Remediation Recommended	
16	2087-1	1	1	Across from 145	WC	OASIS	Left bottle filler	<1 ppb	<1 ppb	6/16/2026 7:00:00 AM	No Further Action	
17	2087-2	1	1	Across from 145	WC	OASIS	Left fountain	<1 ppb	<1 ppb	6/16/2026 7:00:00 AM	No Further Action	
18	2087-3	1	1	Across from 145	WC	OASIS	Right fountain	<1 ppb	<1 ppb	6/16/2026 7:00:00 AM	No Further Action	
19	2087-8	1	1	147	CF		Front of classroom, right of fridge	<1 ppb	<1 ppb	6/16/2026 7:00:00 AM	No Further Action	
20	2087-9	1	1	149	CF		Front of classroom, left of fridge	<1 ppb	<1 ppb	6/16/2026 7:00:00 AM	No Further Action	
21	2087-10	1	1	151	CF		Front of classroom, right of fridge	<1 ppb	<1 ppb	6/16/2026 7:15:00 AM	No Further Action	
22	2087-11	1	1	152	CF		Front of classroom, right of fridge	<1 ppb	<1 ppb	6/16/2026 7:15:00 AM	No Further Action	
23	2087-14	1	1	110	CF		Front of classroom, right of fridge	<1 ppb	<1 ppb	6/16/2026 7:15:00 AM	No Further Action	
24	2087-16	1	1	107	CF		Front of classroom, right of fridge	<1 ppb	<1 ppb	6/16/2026 7:15:00 AM	No Further Action	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
25	2087-12	1	1	142	WC	ELKAY	Bottle filler	<1 ppb	<1 ppb	6/16/2026 7:15:00 AM	No Further Action	
26	2087-15	1	1	109	CF		Front of classroom, left of fridge	<1 ppb	<1 ppb	6/16/2026 7:15:00 AM	No Further Action	
27	2087-19	1	1	126	WC	ELKAY	Bottle filler	<1 ppb	<1 ppb	6/16/2026 7:15:00 AM	No Further Action	
28	2087-20	1	2	Kitchen	KF		Middle kitchen, across from oven	<1 ppb	<1 ppb	6/16/2026 7:15:00 AM	No Further Action	
29	2087-18	1	1	120	WC	ELKAY	Bottle filler	<1 ppb	<1 ppb	6/16/2026 7:15:00 AM	No Further Action	
30	2087-26	1	2	Between 214 and 215	WC	OASIS	Left fountain	<1 ppb	<1 ppb	6/16/2026 7:38:00 AM	No Further Action	
31	2087-25	1	2	Between 214 and 215	WC	OASIS	Left bottle filler	<1 ppb	<1 ppb	6/16/2026 7:38:00 AM	No Further Action	
32	2087-22	1	2	Kitchen	IM	SCOTSMAN	Right side of kitchen	<1 ppb		6/16/2026 7:35:00 AM	No Further Action	
33	2087-31	1	2	Between 249 and 250	WC	OASIS	Left bottle filler	<1 ppb	<1 ppb	6/16/2026 7:38:00 AM	No Further Action	
34	2087-28	1	2	209	CF		Front of classroom, left of fridge	<1 ppb	<1 ppb	6/16/2026 7:38:00 AM	No Further Action	
35	2087-27	1	2	Between 214 and 215	WC	OASIS	Right fountain	<1 ppb	<1 ppb	6/16/2026 7:38:00 AM	No Further Action	
36	2087-29	1	2	207	CF		Front of classroom, left of fridge	<1 ppb	<1 ppb	6/16/2026 7:38:00 AM	No Further Action	
37	2087-32	1	2	Between 249 and 250	WC	OASIS	Left fountain	<1 ppb	<1 ppb	6/16/2026 7:38:00 AM	No Further Action	
38	2087-34	1	2	244	WC	ELKAY	Bottle filler	<1 ppb	<1 ppb	6/16/2026 7:52:00 AM	No Further Action	

[illegible]