



OKLAHOMA DRINKING WATER

**LEAD TESTING**

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

## Duncan Ms Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma Lead in Schools and Child Care Program (LWSC) on 06/11/2026 from 1601 Chisholm Trail Parkway, Duncan, OK 73533.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:

CF: Classroom Faucet

KF: Kitchen Faucet

BF: Bathroom Faucet

NS: Nurse Office Sink

RA: Refrigerator Appliance

OF: Outdoor Faucet

IM: Ice Machine

DW: Drinking Water Fountain

WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

| #  | Outlet ID | Building # | Floor # | Room # / Name       | Outlet Type Code | Water Cooler Make and Model | Comments                                | Initial First Draw Result Final (ppb) | Initial Flush Draw Result Final (ppb) | Initial Sample Date(s) | Action Needed?          | Remediation Action Taken |
|----|-----------|------------|---------|---------------------|------------------|-----------------------------|-----------------------------------------|---------------------------------------|---------------------------------------|------------------------|-------------------------|--------------------------|
| 1  | 4613-6    | 1          | 1       | Kitchen             | KF               |                             | Pot filler                              | 5.8 ppb                               | 2.43 ppb                              | 6/11/2026 6:16:00 AM   | Remediation Recommended |                          |
| 2  | 4613-2    | 1          | 1       | Kitchen             | KF               |                             | Front of kitchen, across from pass bars | 1.69 ppb                              | <1 ppb                                | 6/11/2026 6:00:00 AM   | Remediation Recommended |                          |
| 3  | 4613-3    | 1          | 1       | Kitchen             | KF               |                             | Middle row, across from pot filler      | 1.15 ppb                              | <1 ppb                                | 6/11/2026 6:00:00 AM   | Remediation Recommended |                          |
| 4  | 4613-1    | 1          | 1       | Kitchen             | KF               |                             | Front of kitchen, left of oven          | 1.14 ppb                              | <1 ppb                                | 6/11/2026 6:00:00 AM   | Remediation Recommended |                          |
| 5  | 4613-4    | 1          | 1       | Kitchen             | KF               |                             | Middle row, 2 compartments              | <1 ppb                                | <1 ppb                                | 6/11/2026 6:00:00 AM   | No Further Action       |                          |
| 6  | 4613-5    | 1          | 1       | Kitchen             | IM               | MANITOWOC                   | Back of kitchen                         | <1 ppb                                |                                       | 6/11/2026 6:00:00 AM   | No Further Action       |                          |
| 7  | 4613-7    | 1          | 1       | Gym                 | WC               | ELKAY EZH2O                 | Top bottle filler                       | <1 ppb                                | <1 ppb                                | 6/11/2026 6:16:00 AM   | No Further Action       |                          |
| 8  | 4613-8    | 1          | 1       | Gym                 | WC               | ELKAY LZS8WSSP              | Bottom fountain                         | <1 ppb                                | <1 ppb                                | 6/11/2026 6:16:00 AM   | No Further Action       |                          |
| 9  | 4613-9    | 1          | 1       | Between 605 and 608 | WC               | ELKAY LZS8WSSP              | Left top bottle filler                  | <1 ppb                                | <1 ppb                                | 6/11/2026 6:16:00 AM   | No Further Action       |                          |
| 10 | 4613-10   | 1          | 1       | Between 605 and 608 | WC               | ELKAY LZS8WSSP              | Left fountain                           | <1 ppb                                | <1 ppb                                | 6/11/2026 6:30:00 AM   | No Further Action       |                          |
| 11 | 4613-11   | 1          | 1       | Between 605 and 608 | WC               | ELKAY LZS8WSSP              | Right fountain                          | <1 ppb                                | <1 ppb                                | 6/11/2026 6:30:00 AM   | No Further Action       |                          |
| 12 | 4613-12   | 1          | 1       | Left of 810         | WC               | ELKAY LZS8WSSP              | Left bottle filler                      | <1 ppb                                | <1 ppb                                | 6/11/2026 6:30:00 AM   | No Further Action       |                          |
| 13 | 4613-13   | 1          | 1       | Left of 810         | WC               | ELKAY LZS8WSSP              | Left fountain                           | <1 ppb                                | <1 ppb                                | 6/11/2026 6:30:00 AM   | No Further Action       |                          |
| 14 | 4613-14   | 1          | 1       | Left of 810         | WC               | ELKAY LZS8WSSP              | Right fountain                          | <1 ppb                                | <1 ppb                                | 6/11/2026 6:30:00 AM   | No Further Action       |                          |

[illegible]