



Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action	First Draw (µg/L)	Flush (µg/L)
		Initial Sampling			Resampling	
Non-Detect (<1.0 µg/L)						
1-1-HALL-BF2	Downstairs hallway, RIGHT bathroom faucet	<1.0	<1.0	N/A		
1-1-LUNCH-DW1	Lunchroom drinking fountain	<1.0	<1.0	N/A		
1-1-LUNCH-KF1	Lunchroom kitchen sink	<1.0	<1.0	N/A		
1-2-UHALL-BF1	Upstairs hallway LEFT bathroom faucet	<1.0	<1.0	N/A		
1-2-UHALL-BF2	Upstairs hallway RIGHT bathroom faucet	<1.0	<1.0	N/A		
1-2-UHALL-DW1	Upstairs hallway drinking fountain	3.4	1.7	Replaced	<1.0	<1.0
Low Detection (1.0 - 14.9 µg/L)						

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action	First Draw (µg/L)	Flush (µg/L)
		Initial Sampling			Resampling	
1-1-HALL-BF1	Downstairs hallway, LEFT bathroom faucet	1.1	<1.0	Handwash ONLY		
1-2-URR-BF2	Upstairs restroom RIGHT bathroom faucet	1.8	<1.0	Handwash ONLY		
1-2-URR-BF1	Upstairs restroom LEFT bathroom faucet	2.2	<1.0	Handwash ONLY		
1-2-EAST-OF1	Outside faucet east side of building	16.7	<1.0	Not used for consumption	2.9	<1.0