



RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at Greater New Zion Baptist Church on July 30, 2025. Overall, eight (8) outlets were tested resulting in a total of sixteen (16) samples being sent to the lab.

- Twelve (12) samples had no detectable level of lead.
- Four (4) samples had a low detection of lead between 1.0 and 14.9 µg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 µg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as µg/L. For more information on how to read this report, please see our **Results Interpretation Fact Sheet**.

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
Non-Detect (<1.0 µg/L)				
1-1-KIT-KF2	Kitchen faucet; kitchen; sprayer in 3 compartment sink on back left wall	<1.0	<1.0	N/A
1-1-KIT-IM1	Ice machine; in kitchen	<1.0	<1.0	N/A
1-1-BRR-BF1	Bathroom faucet; boys restroom	<1.0	<1.0	N/A
1-1-GRR-BF1	Bathroom faucet; girls restroom; left faucet	<1.0	<1.0	N/A
1-1-GRR-BF2	Bathroom faucet; girls restroom; right faucet	<1.0	<1.0	N/A
Low Detection (1.0 - 14.9 µg/L)				
1-1-KIT-KF1	Kitchen faucet; kitchen; faucet in 3 compartment sink on back left wall	1.2	<1.0	
1-1-HALL-WC1	Water cooler; Head Start hallway; between boys and girls restroom	1.7	3.0	
1-1-KIT-KF3	Kitchen faucet; kitchen; faucet in single compartment	3.7	<1.0	