



OKLAHOMA DRINKING WATER

LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

District: UCAP, Inc.
School: Hominy Head Start
Sampling Date: 8/6/2025
Status: Remediation

RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at UCAP, Inc. - Hominy Head Start on August 6, 2025. Overall, sixteen (16) outlets were tested resulting in a total of thirty-two (32) samples being sent to the lab.

- Twenty-seven (27) samples had no detectable level of lead.
- Five (5) samples had a low detection of lead between 1.0 and 14.9 µg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 µg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as µg/L. For more information on how to read this report, please see our **Results Interpretation Fact Sheet**.

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
Non-Detect (<1.0 µg/L)				
1-1-KIT-KF1	Kitchen faucet; kitchen; faucet in 3 compartment sink	<1.0	<1.0	N/A
1-1-KIT-KF2	Kitchen faucet; kitchen; sprayer in 3 compartment sink	<1.0	<1.0	N/A
1-1-BATH-BF1	Bathroom faucet; bathroom in hallway right of lobby	<1.0	<1.0	N/A
1-1-HALL-KF1	Kitchen faucet; hallway kitchen area; faucet in 2 compartment sink	<1.0	<1.0	N/A
1-1-HALL-KF2	Kitchen faucet; Hallway kitchen area; sprayer in 2 compartment sink	<1.0	<1.0	N/A
1-1-EHS2-CF1	Classroom faucet; Early Head Start Room 2; white faucet on left wall	<1.0	<1.0	N/A
1-1-EHS2-CF2	Classroom faucet; Early Head Start Room 2; silver faucet in 2 compartment sink on back wall	<1.0	<1.0	N/A
1-1-EHS2-CF3	Classroom faucet; Early Head Start Room 2; sprayer in 2 compartment sink on back wall	<1.0	<1.0	N/A
1-2-EHS1-BF2	Bathroom faucet; Early Head Start Room 1; faucet in adult restroom	<1.0	<1.0	N/A
1-1-HS1-BF1	Bathroom faucet; Head Start Room 1; white faucet in children's bathroom	<1.0	<1.0	N/A

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
1-1-HS1-CF1	Classroom faucet; Head Start Room 1; left faucet outside of bathroom	<1.0	<1.0	N/A
Low Detection (1.0 - 14.9 µg/L)				
1-2-EHS1-CF1	Classroom faucet; Early Head Start Room 1; single silver faucet right of door	1.1	<1.0	
1-1-EHS2-BF1	Bathroom faucet; Early Head Start Room 2; faucet in bathroom	1.2	<1.0	
1-2-EHS1-BF1	Bathroom faucet; Early Head Start Room 1; faucet in bathroom	1.7	<1.0	
1-1-KIT-KF3	Kitchen faucet; kitchen; single silver faucet right of fridges	1.9	<1.0	
1-2-EHS1-CF2	Classroom faucet; Early Head Start Room 1; white faucet between bathrooms	7.3	<1.0	