



OKLAHOMA DRINKING WATER

LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

District: Sunbeam Family Services
School: Metro Tech Early Education Center
Sampling Date: 10/11/2024
Status: Completed Sampling

RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at Sunbeam Family Services - Metro Tech Early Education Center on October 11, 2024. Overall, twenty-four (24) outlets were tested resulting in a total of forty-eight (48) samples being sent to the lab.

- Forty-seven (47) samples had no detectable level of lead.
- One (1) sample had a low detection of lead between 1.0 and 14.9 µg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 µg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as µg/L. For more information on how to read this report, please see our **Results Interpretation Fact Sheet**.

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
Non-Detect (<1.0 µg/L)				
1-1-KIT-IM1	Ice machine in facility kitchen	<1.0	<1.0	N/A
1-1-KIT-KF1	Kitchen faucet in facility kitchen; across from stove	<1.0	<1.0	N/A
1-1-123-CF1	Classroom faucet in Rm 123; left sink	<1.0	<1.0	N/A
1-1-123-CF2	Classroom faucet in Rm 123; middle sink	<1.0	<1.0	N/A
1-1-123-KF1	Kitchen faucet in Rm 123; right sink	<1.0	<1.0	N/A
1-1-120-KF1	Kitchen faucet in Rm 120; left sink	<1.0	<1.0	N/A
1-1-120-KF2	Kitchen faucet in Rm 120; middle sink	<1.0	<1.0	N/A
1-1-120-CF1	Classroom faucet in Rm 120; right sink	<1.0	<1.0	N/A
1-1-120-BF1	Bathroom faucet in Rm 120 bathroom	<1.0	<1.0	N/A
1-1-116-CF2	Classroom faucet in Rm 116; left sink	<1.0	<1.0	N/A
1-1-116-CF1	Classroom faucet in Rm 116; middle sink	<1.0	<1.0	N/A
1-1-116-CF3	Classroom faucet in Rm 116; right sink	<1.0	<1.0	N/A
1-1-116-BF1	Bathroom faucet in Rm 116 bathroom	<1.0	<1.0	N/A

of 2

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
1-1-113-CF1	Classroom faucet in Rm 113; left sink	<1.0	<1.0	N/A
1-1-113-CF2	Classroom faucet in Rm 113; middle sink	<1.0	<1.0	N/A
1-1-113-CF3	Classroom faucet in Rm 113; right sink	<1.0	<1.0	N/A
1-1-113-BF1	Bathroom faucet in Rm 113 bathroom	<1.0	<1.0	N/A
1-1-110-CF2	Classroom faucet in Rm 110; middle sink	<1.0	<1.0	N/A
1-1-110-CF3	Classroom faucet in Rm 110; right sink	<1.0	<1.0	N/A
1-1-110-BF1	Bathroom faucet in Rm 110 bathroom	<1.0	<1.0	N/A
1-1-108-IM1	Ice machine in teachers' lounge	<1.0	<1.0	N/A
1-1-108-WC1	Scotsman water filler in teacher's lounge	<1.0	<1.0	N/A
1-1-108-KF1	Kitchen faucet in teachers' lounge	<1.0	<1.0	N/A
Low Detection (1.0 - 14.9 µg/L)				
1-1-KIT-KF2	Kitchen faucet in facility kitchen; pot filler	1.8	<1.0	