

District: <u>Sunbeam Family Services</u> School: <u>Millwood Early Education Center</u> Sampling Dates: <u>5/17/2024</u>, <u>6/13/2025</u>

Status: Complete

RESULTS

Below are the results from the first and second rounds of testing of drinking water for lead that was conducted at Sunbeam Family Services – Millwood Early Education Center. The initial sampling event occurred on May 17, 2024. The resampling event occurred on June 13, 2025.

In the initial sampling, eleven (11) outlets were tested resulting in a total of twenty-two samples being sent to the lab.

- Twenty-one (21) samples had no detectable level of lead.
- One (1) sample had a low detection of lead between 1.0 and 14.9 μg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 μg/L.

In the resampling, eleven (11) outlets were tested resulting in a total of twenty-two (22) samples being sent to the lab.

- Twenty-two (22) samples had no detectable level of lead.
- Zero (0) samples had a low detection of lead between 1.0 and 14.9 μg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 μg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as $\mu g/L$. For more information on how to read this report, please see our **Results Interpretation** Fact Sheet.

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action	First Draw (µg/L)	Flush (µg/L)			
	NI DA A		Resair	Resampling					
Non-Detect (<1.0 μg/L)									
1-1-TL-KF	Kitchen faucet in teachers' lounge	<1.0	<1.0	N/A	<1.0	<1.0			
1-1-TL-IM	Manitowoc ice machine in teachers' lounge	<1.0	<1.0	N/A	<1.0	<1.0			
1-1-A-CF1	Classroom faucet in Classroom A; left side	<1.0	<1.0	N/A	<1.0	<1.0			
1-1-A-CF2	Classroom faucet in Classroom A; right side	<1.0	<1.0	N/A	<1.0	<1.0			
1-1-B-CF1	Classroom faucet in Classroom B; left side	<1.0	<1.0	N/A	<1.0	<1.0			
1-1-B-CF2	Classroom faucet in Classroom B; right side	<1.0	<1.0	N/A	<1.0	<1.0			
1-1-B-BF	Bathroom faucet in Classroom B Bathroom	<1.0	<1.0	N/A	<1.0	<1.0			

District: <u>Sunbeam Family Services</u> School: <u>Millwood Early Education Center</u> Page

2 of 2

Sample ID	Outlet Description	First Draw (µg/L)	Flush (μg/L)	Remedial Action	First Draw (µg/L)	Flush (μg/L)
		In	itial Sar	Resampling		
1-1-C-CF1	Classroom faucet in	<1.0	<1.0	N/A	<1.0	<1.0
	Classroom C; left side					
1-1-C-CF2	Classroom faucet in	<1.0	<1.0	N/A	<1.0	<1.0
	Classroom C; right side					
1-1-C-BF	Bathroom faucet in Classroom	<1.0	<1.0	N/A	<1.0	<1.0
	C Bathroom					
1-1-A-BF	Bathroom faucet in Classroom A Bathroom	1.4	<1.0		<1.0	<1.0