

Uniform Building Code Commission Staff Comment Form - FGMP 25

FGMP Technical Committee

Review of the 2021 Editions of the International Fuel Gas Code[®] (IFGC[®]), International Mechanical Code[®] (IMC[®]), International Plumbing Code[®] (IPC[®])

NOTE: This form and any attachments hereto are subject to the Oklahoma Open Records Act and may be disbursed, upon request, without further notice to the submitter.

Contact Information:

Originating Committee: FGMP 2015Code Modified: 2018 IPCOriginal Comment Form Number: FGMP 14Rule Number: 748:20-16-8 (4), (7)

Which area of the code (Section, Table, Figure) was revised?

Chapter 3, Section 312.10.1	Page Number: <u>3-6</u>
<u>enupter 5, 500000 512.10.1</u>	i uge i uniberi. <u> </u>

Previous Change:

312.10.1 Inspections. Annual inspections shall be made of all backflow prevention assemblies and air gaps to determine whether the assemblies are operable and air gaps exist, in accordance with Chapter 1, Sections 104.3 and 105.3.2.

Historical information

This modification was made by the 2015 FGMP committee. The change gave the AHJ the ability to allow for a third party agency to do the annual inspection of the backflow preventer.