



OKLAHOMA DRINKING WATER

# LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

District: INCA Community Services

School: Oakland 3-4 Head Start

Sampling Date: 8/28/2024

Status: Remediation

## RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at INCA Community Services - Oakland 3-4 Head Start on August 28, 2024. Overall, six (6) outlets were tested resulting in a total of twelve (12) samples being sent to the lab.

- Seven (7) samples had no detectable level of lead.
- Five (5) samples had a low detection of lead between 1.0 and 14.9 µg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 µg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as µg/L. For more information on how to read this report, please see our **Results Interpretation Fact Sheet**.

Sample ID	Comments	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
<b>Non-Detect (&lt;1.0 µg/L)</b>				
1-1-BR-BF1	Bathroom faucet in boys' restroom	<1.0	<1.0	N/A
1-1-GR-BF1	Bathroom faucet in girls' restroom	<1.0	<1.0	N/A
<b>Low Detection (1.0 - 14.9 µg/L)</b>				
1-1-HB-BF1	Bathroom faucet in HeadStart bathroom	1.27	<1.0	
1-1-KIT-KF2	Kitchen faucet in facility kitchen; solo sink	<1.0	2.17	
1-1-KIT-KF1	Kitchen faucet in facility kitchen; next to dish sprayer; right side of wall	2.85	1.55	
1-1-EH-CF1	Classroom faucet in future Early HeadStart room	3.09	<1.0	