



OKLAHOMA DRINKING WATER

LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

District: Sunbeam Family Services
School: Linwood Early Learning Center
Sampling Date: 10/10/2024
Status: Remediation

RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at Sunbeam Family Services - Linwood Early Learning Center on October 10, 2024. Overall, nine (9) outlets were tested resulting in a total of eighteen (18) samples being sent to the lab.

- Thirteen (13) samples had no detectable level of lead.
- Five (5) samples had a low detection of lead between 1.0 and 14.9 µg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 µg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as µg/L. For more information on how to read this report, please see our **Results Interpretation Fact Sheet**.

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
Non-Detect (<1.0 µg/L)				
1-1-ST-CF1	Starlight back left classroom faucet	<1.0	<1.0	N/A
1-1-SP-CF2	Sparkles middle classroom faucet	<1.0	<1.0	N/A
1-1-SP-CF3	Sparkles right classroom faucet	<1.0	<1.0	N/A
1-1-SW-CF1	Star walker front classroom faucet	<1.0	<1.0	N/A
1-1-SS-CF1	Shining star back left classroom faucet	<1.0	<1.0	N/A
1-1-SS-CF2	Shining star back right classroom faucet	<1.0	<1.0	N/A
Low Detection (1.0 - 9.9 µg/L)				
1-1-SW-CF2	Star walker back classroom faucet	1.3	1.1	
1-1-SP-CF1	Sparkles left classroom faucet	6.2	<1.0	
Borderline (10.0-14.9 µg/L)				
1-1-ST-CF2	Starlight back right classroom faucet	14.2	1.8	