



District: Sunbeam Family Services
School: Tony Reyes Child Development Center
Sampling Date: 10/11/2024
Status: Complete

RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at Sunbeam Family Services - Tony Reyes Child Development Center on October 11, 2024. Overall, seven (7) outlets were tested resulting in a total of fourteen (14) samples being sent to the lab.

- Fourteen (14) samples had no detectable level of lead.
- Zero (0) samples had a low detection of lead between 1.0 and 14.9 µg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 µg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as µg/L. For more information on how to read this report, please see our **Results Interpretation Fact Sheet**.

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
Non-Detect (<1.0 µg/L)				
1-1-L-BF1	Bathroom faucet in Room L Bathroom	<1.0	<1.0	N/A
1-1-B-BF1	Bathroom faucet in Room B Bathroom	<1.0	<1.0	N/A
1-1-A-CF1	Classroom faucet in Room A	<1.0	<1.0	N/A
1-1-G-CF1	Classroom faucet in Room G	<1.0	<1.0	N/A
1-1-F-CF1	Classroom faucet in Room F	<1.0	<1.0	N/A
1-1-C-BF1	Bathroom faucet in Room C Bathroom	<1.0	<1.0	N/A
1-1-KIT-KF1	Kitchen faucet in facility kitchen	<1.0	<1.0	N/A