

District: <u>Tulsa Educare</u> School: <u>Hawthorne Location</u> Sampling Date: <u>3/14/2025</u> Status: Remediation

RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at Tulsa Educare - Hawthorne Location on March 14, 2025. Overall, fifty-two (52) outlets were tested resulting in a total of one hundred four (104) samples being sent to the lab.

- Eighty-three (83) samples had no detectable level of lead.
- Twenty-one (21) samples had a low detection of lead between 1.0 and 14.9 μg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 μg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as $\mu g/L$. For more information on how to read this report, please see our **Results Interpretation** Fact Sheet.

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action		
		Initial Sampling				
Non-Detect (<1.0 μg/L)						
1-1-KIT-IM1	Ice machine in facility kitchen	<1.0	<1.0	N/A		
1-1-HALL-DW1	Drinking water fountain in hall; outside kitchen; left side	<1.0	<1.0	N/A		
1-1-HALL-DW2	Drinking water fountain in hall; outside kitchen; right side	<1.0	<1.0	N/A		
1-1-TL-CF1	Classroom faucet in teachers' lounge	<1.0	<1.0	N/A		
1-1-1/3-CF1	Classroom faucet in Rm 1/3; far right side	<1.0	<1.0	N/A		
1-1-1/3-CF2	Classroom faucet in Rm 1/3; right faucet of double sink	<1.0	<1.0	N/A		
1-1-1/3-CF3	Classroom faucet in Rm 1/3; left faucet of double sink	<1.0	<1.0	N/A		
1-1-1/3-CF4	Classroom faucet in Rm 1/3; single sink on left side	<1.0	<1.0	N/A		
1-1-2/4-CF1	Classroom faucet in Rm 2/4; far right side	<1.0	<1.0	N/A		
1-1-2/4-CF2	Classroom faucet in Rm 2/4; right faucet of double sink	<1.0	<1.0	N/A		
1-1-2/4-CF3	Classroom faucet in Rm 2/4; left faucet of double sink	<1.0	<1.0	N/A		
1-1-2/4-CF4	Classroom faucet in Rm 2/4; single sink on left side	<1.0	<1.0	N/A		

Sample ID	Outlet Description	First Draw (µg/L)	Flush (μg/L)	Remedial Action
		Initial Sampling		
1-1-5/7-CF1	Classroom faucet in Rm 5/7; far right side	<1.0	<1.0	N/A
1-1-5/7-CF2	Classroom faucet in Rm 5/7; right faucet of double sink	<1.0	<1.0	N/A
1-1-5/7-CF4	Classroom faucet in Rm 5/7; single sink on left side	<1.0	<1.0	N/A
1-1-5/7-CF5	Classroom faucet in Rm 5/7; far left side	<1.0	<1.0	N/A
1-1-6/8-CF1	Classroom faucet in Rm 6/8; far left side	<1.0	<1.0	N/A
1-1-6/8-CF2	Classroom faucet in Rm 6/8; single sink on left side	<1.0	<1.0	N/A
1-1-6/8-CF3	Classroom faucet in Rm 6/8; left faucet of double sink	<1.0	<1.0	N/A
1-1-6/8-CF4	Classroom faucet in Rm 6/8; right faucet of double sink	<1.0	<1.0	N/A
1-1-9/11-CF2	Classroom faucet in Rm 9/11; right faucet of double sink	<1.0	<1.0	N/A
1-1-9/11-CF4	Classroom faucet in Rm 9/11; single sink on left side	<1.0	<1.0	N/A
1-1-9/11-CF5	Classroom faucet in Rm 9/11; far left side	<1.0	<1.0	N/A
1-1-10/12-CF1	Classroom faucet in Rm 10/12; far left side	<1.0	<1.0	N/A
1-1-10/12-CF2	Classroom faucet in Rm 10/12; single sink on left side	<1.0	<1.0	N/A
1-1-10/12-CF3	Classroom faucet in Rm 10/12; left faucet of double sink	<1.0	<1.0	N/A
1-1-10/12-CF4	Classroom faucet in Rm 10/12; right faucet of double sink	<1.0	<1.0	N/A
1-1-13/15-CF2	Classroom faucet in Rm 13/15; right faucet of double sink	<1.0	<1.0	N/A
1-1-13/15-CF3	Classroom faucet in Rm 13/15; left faucet of double sink	<1.0	<1.0	N/A
1-1-13/15-CF4	Classroom faucet in Rm 13/15; single sink on left side	<1.0	<1.0	N/A
1-1-13/15-CF5	Classroom faucet in Rm 13/15; far left side	<1.0	<1.0	N/A
1-1-14/16-CF1	Classroom faucet in Rm 14/16; far left side	<1.0	<1.0	N/A
1-1-14/16-CF2	Classroom faucet in Rm 14/16; single sink on left side	<1.0	<1.0	N/A

District: <u>Tulsa Educare</u>

Page 3 of 3

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
1-1-14/16-CF4	Classroom faucet in Rm 14/16; right faucet of double sink	<1.0	<1.0	N/A
1-1-14/16-CF5	Classroom faucet in Rm 14/16; far right side	<1.0	<1.0	N/A
	Low Detection (1.0 - 14.9 μg	:/L)		
1-1-KIT-KF4	Kitchen faucet in facility kitchen; sink in center console	1.0	<1.0	
1-1-2/4-CF5	Classroom faucet in Rm 2/4; far left side	1.0	<1.0	
1-1-10/12-CF5	Classroom faucet in Rm 10/12; far right side	1.0	<1.0	
1-1-9/11-CF1	Classroom faucet in Rm 9/11; far right side	1.1	<1.0	
1-1-1/3-CF5	Classroom faucet in Rm 1/3; far left side	1.1	<1.0	
1-1-14/16-CF3	Classroom faucet in Rm 14/16; left faucet of double sink	1.1	<1.0	
1-1-KIT-KF5	Kitchen faucet in facility kitchen; sink on interior wall	1.2	<1.0	
1-1-13/15-CF1	Classroom faucet in Rm 13/15; far right side	1.6	<1.0	
1-1-6/8-CF5	Classroom faucet in Rm 6/8; far right side	1.6	<1.0	
1-1-5/7-CF3	Classroom faucet in Rm 5/7; left faucet of double sink	1.9	<1.0	
1-1-HALL-DW3	Drinking water fountain in hall; near Rms 1/3 and 5/7; left side	2.5	1.6	
1-1-HALL-DW4	Drinking water fountain in hall; near Rms 1/3 and 5/7; right side	2.5	<1.0	
1-1-9/11-CF3	Classroom faucet in Rm 9/11; left faucet of double sink	2.7	<1.0	
1-1-KIT-KF2	Kitchen faucet in facility kitchen; kettle pot filler in back	3.2	2.5	
1-1-KIT-KF1	Kitchen faucet in facility kitchen; sink on back wall near exit	4.3	<1.0	
1-1-KIT-KF3	Kitchen faucet in facility kitchen; sprayer pot filler in back	4.6	1.8	
1-1-KIT-KF6	Kitchen faucet in facility kitchen; sprayer attachment of sink on interior wall	4.7	1.1	