



OKLAHOMA DRINKING WATER

LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Central Jhs Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma Lead in Schools and Child Care Program (LWSC) on 07/24/2026 from 400 North Broadway Street, Moore, OK 73160.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:

CF: Classroom Faucet

KF: Kitchen Faucet

BF: Bathroom Faucet

NS: Nurse Office Sink

RA: Refrigerator Appliance

OF: Outdoor Faucet

IM: Ice Machine

DW: Drinking Water Fountain

WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	3457-49	3	1	Old gym - main room	WC	Elkay	Near back of gym	87.3 ppb	44.1 ppb	07/24/2026 09:15	Remediation Strongly Suggested	
2	3457-6	900	1	Bathrooms across from 930	WC	Elkay	Left short fountain	6.59 ppb	<1 ppb	07/24/2026 07:22	Remediation Recommended	
3	3457-22	700	1	Near back of building	WC	Elkay	Bottle filler - Near back of building	4.79 ppb	2.93 ppb	07/24/2026 08:19	Remediation Recommended	
4	3457-2	1	1	Cafeteria	KF			3.43 ppb	<1 ppb	07/24/2026 06:37	Remediation Recommended	
5	3457-1	1	1	Cafeteria	KF		2nd sink right side of the kitchen	3.41 ppb	<1 ppb	07/24/2026 06:33	Remediation Recommended	
6	3457-3	1	1	Cafeteria	IM		Ice maker	<1 ppb		07/24/2026 06:39	No Further Action	
7	3457-4	1	1	Cafeteria	WC	Elkay	Bottle filler	<1 ppb	<1 ppb	07/24/2026 06:48	No Further Action	
8	3457-5	1	1	Cafeteria	WC	Elkay	Fountain below bottle filler	<1 ppb	<1 ppb	07/24/2026 06:55	No Further Action	
9	3457-9	900	1	Bathrooms near library	WC	Elkay	Far left fountain	<1 ppb	<1 ppb	07/24/2026 07:34	No Further Action	
10	3457-7	900	1	Bathrooms across from room 930	WC	Elkay	Water spout	<1 ppb	<1 ppb	07/24/2026 07:24	No Further Action	
11	3457-8	900	1	Bathrooms across from 930	WC	Elkay	Solo fountain in corner	<1 ppb	<1 ppb	07/24/2026 07:29	No Further Action	
12	3457-12	900	1	Hallway near trophy window across from garden	WC	Elkay	Left fountain	<1 ppb	<1 ppb	07/24/2026 07:43	No Further Action	
13	3457-15	900	1	Bathrooms near rm 901	WC	Elkay	Middle fountain	<1 ppb	<1 ppb	07/24/2026 07:56	No Further Action	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
14	3457-11	900	1	Bathrooms near library	WC	Elkay	Far right fountain	<1 ppb	<1 ppb	07/24/2026 07:38	No Further Action	
15	3457-14	900	1	Bathrooms next to rm 901	WC	Elkay	Far left fountain	<1 ppb	<1 ppb	07/24/2026 07:52	No Further Action	
16	3457-13	900	1	Hallway near trophy window across from garden	WC	Elkay	Right fountain	<1 ppb	<1 ppb	07/24/2026 07:48	No Further Action	
17	3457-18	900	1	Near trophy case and counseling center	WC	Elkay	Right fountain	<1 ppb	<1 ppb	07/24/2026 08:09	No Further Action	
18	3457-17	900	1	Near trophy case and counseling center	WC	Elkay	Bottle filler only	<1 ppb	<1 ppb	07/24/2026 08:04	No Further Action	
19	3457-16	900	1	Bathrooms near rm 901	WC	Elkay	Far right fountain	<1 ppb	<1 ppb	07/24/2026 07:58	No Further Action	
20	3457-24	1	1	Fieldhouse near boys locker room.	WC	Elkay	Fountain under bottle filler	<1 ppb	<1 ppb	07/24/2026 07:58	No Further Action	
21	3457-25	1	1	Fieldhouse near boys locker room.	WC	Elkay	Fountain to the left of bottle filler	<1 ppb	<1 ppb	07/24/2026 08:00	No Further Action	
22	3457-26	1	1	Fieldhouse weight room	WC	Elkay	Bottle Filler	<1 ppb	<1 ppb	07/24/2026 08:06	No Further Action	
23	3457-27	1	1	Fieldhouse weight room	WC	Elkay	Fountain under bottle filler	<1 ppb	<1 ppb	07/24/2026 08:10	No Further Action	
24	3457-28	1	1	Fieldhouse weight room	WC	Elkay	Fountain to the left of bottle filler	<1 ppb	<1 ppb	07/24/2026 08:12	No Further Action	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
25	3457-29	2	1	New Gym - main entrance concessions	WC	Elkay	Fountain to left of bottle filler	<1 ppb	<1 ppb	07/24/2026 08:28	No Further Action	
26	3457-30	2	1	New Gym - main entrance concessions	WC	Elkay	Bottle Filler	<1 ppb	<1 ppb	07/24/2026 08:30	No Further Action	
27	3457-31	2	1	New Gym - main entrance concessions	WC	Elkay	Fountain under bottle filler	<1 ppb	<1 ppb	07/24/2026 08:32	No Further Action	
28	3457-32	2	1	New gym - girls locker room	WC	Elkay	Fountain to left of bottle filler	<1 ppb	<1 ppb	07/24/2026 08:36	No Further Action	
29	3457-33	2	1	New gym - girls locker room	WC	Elkay	Bottle Filler	<1 ppb	<1 ppb	07/24/2026 08:37	No Further Action	
30	3457-34	2	1	New gym - girls locker room	WC	Elkay	Fountain under bottle filler	<1 ppb	<1 ppb	07/24/2026 08:39	No Further Action	
31	3457-38	2	1	New Gym - Girls basketball locker room	WC	Elkay	Left fountain	<1 ppb	<1 ppb	07/24/2026 08:48	No Further Action	
32	3457-39	2	1	New Gym - Girls basketball locker room	WC	Elkay	Bottle Filler	<1 ppb	<1 ppb	07/24/2026 08:50	No Further Action	
33	3457-40	2	1	New Gym - Girls basketball locker room	WC	Elkay	Fountain below bottle filler	<1 ppb	<1 ppb	07/24/2026 08:52	No Further Action	
34	3457-41	2	1	New Gym - boys locker room	WC	Elkay	Left fountain	<1 ppb	<1 ppb	07/24/2026 08:57	No Further Action	

#	Outlet ID	Buildin g #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
35	3457-42	2	1	New Gym - boys locker room	WC	Elkay	Left fountain	<1 ppb	<1 ppb	07/24/2026 08:58	No Further Action	
36	3457-43	2	1	New Gym - boys locker room	WC	Elkay	Fountain below bottle filler	<1 ppb	<1 ppb	07/24/2026 09:01	No Further Action	
37	3457-45	2	1	New gym - boys basketball locker room	WC	Elkay	Bottle Filler	<1 ppb	<1 ppb	07/24/2026 09:06	No Further Action	
38	3457-47	3	1	Old gym hallway	WC	Elkay	Fountain below bottle filler	<1 ppb	<1 ppb	07/24/2026 09:10	No Further Action	
39	3457-48	3	1	Old gym hallway	WC	Elkay	Bottle filler	<1 ppb	<1 ppb	07/24/2026 09:12	No Further Action	
40	3457-50	800	1	Across from rm 812	WC	Elkay	Left tall fountain	<1 ppb	<1 ppb	07/24/2026 09:24	No Further Action	
41	3457-51	800	1	Across from rm 812	WC	Elkay	Right short fountain	<1 ppb	<1 ppb	07/24/2026 09:28	No Further Action	
42	3457-52	800	1	Wall with 3 fountains - across rm 803	WC	Elkay	Bottle filler	<1 ppb	<1 ppb	07/24/2026 09:30	No Further Action	
43	3457-53	800	1	Wall with 3 fountains - across rm 803	WC	Elkay	Fountain under bottle filler	<1 ppb	<1 ppb	07/24/2026 09:33	No Further Action	
44	3457-54	800	1	Wall with 3 fountains - across rm 803	WC	Elkay	Right fountain	<1 ppb	<1 ppb	07/24/2026 09:35	No Further Action	
45	3457-36	2	1	New Gym - girls volleyball locker room	WC	Elkay	Bottle Filler - Not Working	<1 ppb, <1 ppb		07/24/2026 08:45, 07/24/2026 08:45	#ERROR!	

[illegible]