



OKLAHOMA DRINKING WATER

LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Perkins-Tryon Es Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma
Lead in Schools and Child Care Program (LWSC) on 07/01/2026
from 1008 E Kirk, Perkins, OK 74059.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:

CF: Classroom Faucet

KF: Kitchen Faucet

BF: Bathroom Faucet

NS: Nurse Office Sink

RA: Refrigerator Appliance

OF: Outdoor Faucet

IM: Ice Machine

DW: Drinking Water Fountain

WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	4401-25	1	1	155	CF		Single faucet	15.7 ppb	<1 ppb	7/1/2026 7:20:00 AM	Remediation Strongly Suggested	
2	4401-17	1	1	147	CF		Single faucet	11.6 ppb	1.88 ppb	7/1/2026 6:55:00 AM	Remediation Strongly Suggested	
3	4401-21	1	1	148	CF		Single faucet	9.5 ppb	1.3 ppb	7/1/2026 6:55:00 AM	Remediation Recommended	
4	4401-19	1	1	146	CF		Single faucet	9.28 ppb	1.72 ppb	7/1/2026 6:55:00 AM	Remediation Recommended	
5	4401-39	1	1	138	DW		Bubbler	2.64 ppb	8.01 ppb	7/1/2026 7:41:00 AM	Remediation Recommended	
6	4401-40	1	1	105	DW		Bubbler	6.98 ppb	2.02 ppb	7/1/2026 7:41:00 AM	Remediation Recommended	
7	4401-23	1	1	156	CF		Single faucet	6.6 ppb	1.15 ppb	7/1/2026 7:20:00 AM	Remediation Recommended	
8	4401-35	1	1	128	CF		Faucet on right side of classroom	5.86 ppb	1.21 ppb	7/1/2026 7:41:00 AM	Remediation Recommended	
9	4401-27	1	1	158	CF		Single faucet	5.36 ppb	1.05 ppb	7/1/2026 7:20:00 AM	Remediation Recommended	
10	4401-9	1	1	Kitchen	KF		2 compartment faucet, back of kitchen	5.28 ppb	1.69 ppb	7/1/2026 6:33:00 AM	Remediation Recommended	
11	4401-33	1	1	157	CF		Single faucet	5.1 ppb	1.27 ppb	7/1/2026 7:20:00 AM	Remediation Recommended	
12	4401-20	1	1	146	DW		Bubbler	4.98 ppb	1.78 ppb	7/1/2026 6:55:00 AM	Remediation Recommended	
13	4401-26	1	1	155	DW		Bubbler	4.73 ppb	<1 ppb	7/1/2026 7:20:00 AM	Remediation Recommended	
14	4401-15	1	1	144	CF		Single faucet	4.58 ppb	1.24 ppb	7/1/2026 6:55:00 AM	Remediation Recommended	
15	4401-31	1	1	159	CF		Single faucet	4.07 ppb	<1 ppb	7/1/2026 7:20:00 AM	Remediation Recommended	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
16	4401-22	1	1	148	DW		Bubbler	3.32 ppb	1.77 ppb	7/1/2026 7:20:00 AM	Remediation Recommended	
17	4401-37	1	1	128	CF		Faucet on left side of classroom	3.32 ppb	2.65 ppb	7/1/2026 7:41:00 AM	Remediation Recommended	
18	4401-29	1	1	160	CF		Single faucet	2.35 ppb	<1 ppb	7/1/2026 7:20:00 AM	Remediation Recommended	
19	4401-28	1	1	158	DW		Bubbler	2.15 ppb	<1 ppb	7/1/2026 7:20:00 AM	Remediation Recommended	
20	4401-34	1	1	157	DW		Bubbler	2.12 ppb	1.24 ppb	7/1/2026 7:41:00 AM	Remediation Recommended	
21	4401-18	1	1	147	DW		Bubbler	2.1 ppb	1.44 ppb	7/1/2026 6:55:00 AM	Remediation Recommended	
22	4401-32	1	1	159	DW		Bubbler	1.82 ppb	1.85 ppb	7/1/2026 7:20:00 AM	Remediation Recommended	
23	4401-24	1	1	156	DW		Bubbler	1.8 ppb	<1 ppb	7/1/2026 7:20:00 AM	Remediation Recommended	
24	4401-8	1	1	Kitchen	KF		Pot filler, middle of kitchen	1.73 ppb	1.41 ppb	7/1/2026 6:33:00 AM	Remediation Recommended	
25	4401-36	1	1	128	DW		Bubbler on right side of classroom	1.37 ppb	1.05 ppb	7/1/2026 7:41:00 AM	Remediation Recommended	
26	4401-16	1	1	144	DW		Bubbler	1.34 ppb	1.22 ppb	7/1/2026 6:55:00 AM	Remediation Recommended	
27	4401-38	1	1	128	DW		Bubbler on left side of classroom	1.29 ppb	<1 ppb	7/1/2026 7:41:00 AM	Remediation Recommended	
28	4401-30	1	1	160	DW		Bubbler	<1 ppb	1.22 ppb	7/1/2026 7:20:00 AM	Remediation Recommended	
29	4401-5	1	1	Gym	WC	ELKAY EZH20 LZSTL8WSL P	Right fountain	<1 ppb	<1 ppb	7/1/2026 6:33:00 AM	No Further Action	

[illegible]