



OKLAHOMA DRINKING WATER

LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Perkins-Tryon Ms Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma
Lead in Schools and Child Care Program (LWSC) on 07/01/2026
from 390 W Kenworthy, Perkins, OK 74059.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:

CF: Classroom Faucet

KF: Kitchen Faucet

BF: Bathroom Faucet

NS: Nurse Office Sink

RA: Refrigerator Appliance

OF: Outdoor Faucet

IM: Ice Machine

DW: Drinking Water Fountain

WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	4403-21	3	1	Chior	WC	ELKAY EZFS8_1B	Back of classroom	14.7 ppb	13.2 ppb	7/1/2026 8:25:00 AM	Remediation Strongly Suggested	
2	4403-9	2	1	Kitchen	KF		2 compartment faucet	13.7 ppb	1.31 ppb	7/1/2026 8:02:00 AM	Remediation Strongly Suggested	
3	4403-18	2	1	203	CF		Single faucet	12.7 ppb	5.18 ppb	7/1/2026 8:25:00 AM	Remediation Strongly Suggested	
4	4403-11	2	1	Across from 129	WC	ELKAY EZFS8_1F	Right fountain	3.34 ppb	7.42 ppb	7/1/2026 8:25:00 AM	Remediation Recommended	
5	4403-19	2	1	204	CF		Single faucet	4.22 ppb	5.01 ppb	7/1/2026 8:25:00 AM	Remediation Recommended	
6	4403-12	2	1	212	CF		Kitchen 1 faucet	4.46 ppb	1.01 ppb	7/1/2026 8:25:00 AM	Remediation Recommended	
7	4403-20	3	1	Band	WC	ELKAY EHFS8-1A	Front of classroom	3.14 ppb	2.27 ppb	7/1/2026 8:25:00 AM	Remediation Recommended	
8	4403-14	2	1	212	CF		Kitchen #3 faucet	2.82 ppb	<1 ppb	7/1/2026 8:25:00 AM	Remediation Recommended	
9	4403-13	2	1	212	CF		Kitchen #2 faucet	2.54 ppb	<1 ppb	7/1/2026 8:25:00 AM	Remediation Recommended	
10	4403-8	1	1	Administration office	CF		Single faucet	1.82 ppb	<1 ppb	7/1/2026 8:02:00 AM	Remediation Recommended	
11	4403-2	1	1	Left of 114	WC	ELKAY EZ H20 LZSTL8WSL P	Right fountain	<1 ppb	1.05 ppb	7/1/2026 8:02:00 AM	Remediation Recommended	
12	4403-5	1	1	Across from 111	WC	ELKAY EZ H20 LZSTL8WSL P	Right fountain	<1 ppb	<1 ppb	7/1/2026 8:02:00 AM	No Further Action	
13	4403-4	1	1	Across from 111	WC	ELKAY EZ H20 LZSTL8WSL P	Left fountain	<1 ppb	<1 ppb	7/1/2026 8:02:00 AM	No Further Action	

[illegible]