

RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at Sunbeam Family Services - Pierce Early Education Center on August 15, 2024. Overall, sixty-seven (67) outlets were tested resulting in a total of one hundred thirty-four (134) samples being sent to the lab.

- One hundred seven (107) samples had no detectable level of lead.
- Twenty-three (23) samples had a low detection of lead between 1.0 and 14.9 µg/L.
- Four (4) samples had a high detection of lead equal to or above 15.0 µg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as µg/L. For more information on how to read this report, please see our **Results Interpretation Fact Sheet**.

Sample ID	Comments	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
Non-Detect (<1.0 µg/L)				
1-1-111-BF1	Bathroom faucet in Rm 111 bathroom	<1.0	<1.0	N/A
1-1-120-CF1	Classroom faucet in Rm 120; tall sink; left side	<1.0	<1.0	N/A
1-1-120-CF2	Classroom faucet in Rm 120; tall sink; right side	<1.0	<1.0	N/A
1-1-120-CF3	Classroom faucet in Rm 120; short sink	<1.0	<1.0	N/A
1-1-120-BF1	Bathroom faucet in Rm 120 bathroom	<1.0	<1.0	N/A
1-1-108-KF1	Kitchen faucet in Rm 108; used for making coffee	<1.0	<1.0	N/A
1-1-108-DW1	Scotsman drinking water dispenser in Rm 108; connected to ice machine	<1.0	<1.0	N/A
1-1-121-CF2	Classroom faucet in Rm 121; tall sink; right side	<1.0	<1.0	N/A
1-1-121-CF3	Classroom faucet in Rm 121; short sink	<1.0	<1.0	N/A
1-1-121-BF1	Bathroom faucet in Rm 121 bathroom	<1.0	<1.0	N/A
1-1-KIT-KF1	Kitchen faucet in facility kitchen; 3 compartment sink; only one used for cooking	<1.0	<1.0	N/A
1-1-KIT-IM1	Manitowoc ice machine in kitchen	<1.0	<1.0	N/A

Sample ID	Comments	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
1-1-103-CF1	Classroom faucet in Rm 103; tall sink; left side	<1.0	<1.0	N/A
1-1-125-CF2	Classroom faucet in Rm 125; tall sink; right side	<1.0	<1.0	N/A
1-1-125-CF3	Classroom faucet in Rm 125; short sink	<1.0	<1.0	N/A
1-1-125-BF1	Bathroom faucet in Rm 125 bathroom	<1.0	<1.0	N/A
1-1-148-KF1	Kitchen faucet in main office Rm 148	<1.0	<1.0	N/A
1-1-141-KF1	Kitchen faucet in main office Rm 141	<1.0	<1.0	N/A
1-1-139-CF2	Classroom faucet in Rm 139; tall sink; right side	<1.0	<1.0	N/A
1-1-139-BF1	Bathroom faucet in Rm 139 bathroom	<1.0	<1.0	N/A
1-1-130-CF1	Classroom faucet in Rm 130; tall sink; left side	<1.0	<1.0	N/A
1-1-130-CF2	Classroom faucet in Rm 130; tall sink; right side	<1.0	<1.0	N/A
1-1-130-CF3	Classroom faucet in Rm 130; short sink	<1.0	<1.0	N/A
1-1-130-BF1	Bathroom faucet in Rm 130 bathroom	<1.0	<1.0	N/A
1-1-137-CF1	Classroom faucet in Rm 137; tall sink; left side	<1.0	<1.0	N/A
1-1-137-CF2	Classroom faucet in Rm 137; tall sink; right side	<1.0	<1.0	N/A
1-1-137-CF3	Classroom faucet in Rm 137; short sink	<1.0	<1.0	N/A
1-1-131-CF2	Classroom faucet in Rm 131; tall sink; right side	<1.0	<1.0	N/A
1-1-131-CF3	Classroom faucet in Rm 131; short sink	<1.0	<1.0	N/A
1-1-131-BF1	Bathroom faucet in Rm 131 bathroom	<1.0	<1.0	N/A
1-1-132-CF1	Classroom faucet in Rm 132; tall sink; left side	<1.0	<1.0	N/A
1-1-132-CF2	Classroom faucet in Rm 132; tall sink; right side	<1.0	<1.0	N/A
1-1-132-CF3	Classroom faucet in Rm 132; short sink	<1.0	<1.0	N/A
1-1-132-BF1	Bathroom faucet in Rm 132 bathroom	<1.0	<1.0	N/A
1-1-LIB-CF1	Classroom faucet in library; used for coffee	<1.0	<1.0	N/A

Sample ID	Comments	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
1-1-133-CF1	Classroom faucet in Rm 133; tall sink; left side	<1.0	<1.0	N/A
1-1-133-CF2	Classroom faucet in Rm 133; tall sink; right side	<1.0	<1.0	N/A
1-1-133-CF3	Classroom faucet in Rm 133; short sink	<1.0	<1.0	N/A
1-1-133-BF1	Bathroom faucet in Rm 133 bathroom	<1.0	<1.0	N/A
1-1-GYM-WC1	Elkay water cooler in gym; left side	<1.0	<1.0	N/A
1-1-GYM-WC2	Elkay water cooler in gym; right side	<1.0	<1.0	N/A
1-1-CAT-KF 1	Kitchen faucet in catering kitchen	<1.0	<1.0	N/A
1-1-CAT-IM1	Ice machine in catering kitchen	<1.0	<1.0	N/A
1-1-CAT-DW1	Drinking water dispenser attached to ice machine in catering kitchen	<1.0	<1.0	N/A
1-1-108-IM1	Scotsman ice machine in Rm 108	<1.0	<1.0	N/A
1-1-KIT-KF2	Pot filler in facility kitchen	<1.0	<1.0	N/A
Low Detection (1.0 - 14.9 µg/L)				
1-1-139-CF3	Classroom faucet in Rm 139; short sink	1.1	<1.0	
1-1-HALL-WC1	Elkay water cooler in hall; near Rm 115	1.1	<1.0	
1-1-139-CF1	Classroom faucet in Rm 139; tall sink; left side	1.2	<1.0	
1-1-103-CF2	Classroom faucet in Rm 103; tall sink; right side	1.3	<1.0	
1-1-111-CF1	Classroom faucet in Rm 111; tall sink; left side	1.3	<1.0	
1-1-111-CF3	Classroom faucet in Rm 111; short sink	1.3	<1.0	
1-1-107-KF1	Kitchen faucet in Rm 107	1.4	<1.0	
1-1-131-CF1	Classroom faucet in Rm 131; tall sink; left side	1.4	<1.0	
1-1-121-CF1	Classroom faucet in Rm 121; tall sink; left side	1.8	<1.0	
1-1-HALL-WC3	Elkay water cooler in hall; near Rm 120; right side	2.1	1.5	
1-1-103-BF2	Bathroom faucet in Rm 103 bathroom; right side	2.2	<1.0	
1-1-111-CF2	Classroom faucet in Rm 111; tall sink; right side	2.2	<1.0	

Sample ID	Comments	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
1-1-103-CF3	Classroom faucet in Rm 103; short sink	2.3	<1.0	
1-1-103-BF1	Bathroom faucet in Rm 103 bathroom; left side	3.0	<1.0	
1-1-HALL-WC2	Elkay water cooler in hall; near Rm 120; left side	3.1	2.6	
1-1-137-BF1	Bathroom faucet in Rm 137 bathroom	3.3	<1.0	
1-1-125-CF1	Classroom faucet in Rm 125; tall sink; left side	8.0	<1.0	
High Detection (≥15.0 µg/L)				
1-1-101-BF1	Bathroom faucet in Rm 101 bathroom	17.8	1.4	
1-1-101-CF2	Classroom faucet in Rm 101; tall sink; right side	22.8	1.8	
1-1-101-CF1	Classroom faucet in Rm 101; tall sink; left side	26.0	1.8	
1-1-101-CF3	Classroom faucet in Rm 101; short sink	37.7	2.4	