



# OKLAHOMA

## Uniform Building Code Commission Staff Comment Form - [FGMP 11](#)

### FGMP Technical Committee

Review of the 2021 Editions of the International Fuel Gas Code® (IFGC®), International Mechanical Code® (IMC®), International Plumbing Code® (IPC®)

**NOTE:** This form and any attachments hereto are subject to the Oklahoma Open Records Act and may be disbursed, upon request, without further notice to the submitter.

#### Contact Information:

Name: OUBCC Staff

Date 5/17/23

Email: Kathy.Hehnly@oubcc.ok.gov

Phone: 405-521-6501

#### Code Change Information

Originating Committee: FGMP 2015

Code Modified: 2018 IMC

Original Comment Form Number: FGMP 95  
& 114

Rule Number: 748:20-14-8 (6)

Which area of the code (Section, Table, Figure) was revised?

Chapter 3, Section 305.5.1

Page Number: 3-5

#### Previous Change:

**305.5.1 Location and protection of refrigerant piping.** Refrigerant piping installed within 1 1/2 inches (38 mm) of the underside of roof decks shall be protected from damage caused by nails and other fasteners.

#### Historical information

This section was added by the 2015 FGMP committee to add language for the location and protection of refrigerant piping installed on the underside of roof decks. The language does not exist in the 2021 code.