



OKLAHOMA

Uniform Building Code Commission Staff Comment Form - FGMP 18

FGMP Technical Committee

Review of the 2021 Editions of the International Fuel Gas Code® (IFGC®), International Mechanical Code® (IMC®), International Plumbing Code® (IPC®)

NOTE: This form and any attachments hereto are subject to the Oklahoma Open Records Act and may be disbursed, upon request, without further notice to the submitter.

Contact Information:

Name: OUBCC Staff

Date 5/17/23

Email: Kathy.Hehnly@oubcc.ok.gov

Phone: 405-521-6501

Code Change Information

Originating Committee: FGMP 2015

Code Modified: 2018 IMC

Original Comment Form Number: FGMP 2,
92 & 93

Rule Number: 748:20-14-16

Which area of the code (Section, Table, Figure) was revised?

Chapter 11, Section 1102.3

Page Number: 11-2

Previous Change:

~~**1103.2 Access port protection.** Refrigerant access ports shall be protected in accordance with Section 1101.10 whenever refrigerant is added to or recovered from refrigeration or air-conditioning systems.~~

Historical information

This section was originally modified by the FGMP 2015 committee. In the 2018 adoption the section was stricken from the code due to a lack of ability to enforce and the liability associated with the section. The section exists in the 2021 code. The committee should determine if it should remain stricken in the adoption or if the change should be deleted from the agency's rules and allow the code to revert to the published requirement.