



OKLAHOMA

Uniform Building Code Commission Staff Comment Form - [FGMP 29](#)

FGMP Technical Committee

Review of the 2021 Editions of the International Fuel Gas Code® (IFGC®), International Mechanical Code® (IMC®), International Plumbing Code® (IPC®)

NOTE: This form and any attachments hereto are subject to the Oklahoma Open Records Act and may be disbursed, upon request, without further notice to the submitter.

Contact Information:

Name: OUBCC Staff

Date 5/17/23

Email: Kathy.Hehnlly@oubcc.ok.gov

Phone: 405-521-6501

Code Change Information

Originating Committee: FGMP 2018

Code Modified: 2018 IPC

Original Comment Form Number: SCF 64

Rule Number: 748:20-16-9 (3)

Which area of the code (Section, Table, Figure) was revised?

Chapter 4, Section 408.2

Page Number: 4-7

Previous Change:

408.2 Water connection. The water supply to a bidet shall be protected against backflow by an air gap or backflow preventer in accordance with Section ~~608.13.1, 608.13.2, 608.13.3, 608.13.5, 608.13.6 or 608.13.8~~ 608.14.1, 608.14.2, 608.14.3, 608.14.5, 608.14.6 or 608.14.8.

Historical information

This change was made to correct errata published by ICC. The language is correct in the 2021 code. Staff recommendation is to delete the modification from the agency's rules.