



OKLAHOMA

Uniform Building Code Commission Staff Comment Form - [BEBF 38](#)

BEBF Technical Committee

Review of the 2021 Editions of the International Building Code® (IBC®), International Existing Building Code® (IEBC®), International Fire Code®

NOTE: This form and any attachments hereto are subject to the Oklahoma Open Records Act and may be disbursed, upon request, without further notice to the submitter.

Contact Information:

Name: OUBCC Staff

Date 05/10/23

Email: Kathy.Hehnly@oubcc.ok.gov

Phone: 405-521-6501

Code Change Information

Originating Committee: BEBF 2018

Code Modified: 2018 IBC

Original Comment Form Number: CCF-108, 109, 110, & 11

Rule Number: 748:20-2-21 (2), (3), (4), & (5)

Which area of the code (Section, Table, Figure) was revised?

IBC Ch 16, Figures 1609.3(1), 1609.3(2), 1609.3(3), and 1609.3(4)

Page Number: 2021 IBC 16-20 thru 16-23

Previous change:

Figures 1609.3(1), 1609.3(2), 1609.3(3), and 1609.3(4). The change to each of these figures was to address errata to correct a reference to a website. The change modified the footnotes from www.atcouncil.org/windspeed to www.hazards.atcouncil.org.

The 2021 code figures show the website: www.atcouncil.org/windspeed.

Historical information:

This change was made by the 2018 BEBF committee to address errata published by the ICC. As of 05/10/2023 there is no errata to the 2021 code for these same changes to be made to the 2021 code.

Staff recommendation is for the committee to determine if the published website is correct or if the changes should be kept in the agency rules.