



Uniform Building Code Commission
Staff Comment Form– BEBF 69
BEFB Technical Committee

Review of the 2021 Editions of the International Building Code® (IBC®), International Existing Building Code® (IEBC®), International Fire Code®

NOTE: This form and any attachments hereto are subject to the Oklahoma Open Records Act and may be disbursed, upon request, without further notice to the submitter.

Contact Information:

Name: OUBCC Staff

Date 05/10/23

Email: Kathy.Hehnly@oubcc.ok.gov

Phone: 405-521-6501

Code Change Information

Originating Committee: BEFB 2018

Code Modified: 2018 IFC

Original Comment Form Number: SCF 85

Rule Number: 748:20-4-14 (3)

Which area of the code (Section, Table, Figure) was revised?

IFC Chapter 9, Section 907.2.6.1.1

Page Number: 2021 IFC 9-23

Previous change:

907.2.6.1.1 Smoke alarms. Single- and multiple- station smoke alarms shall be installed in accordance with Section ~~907.2.11~~ 907.2.10.

Historical information

This change to the 2018 code was made to correct errata. The 2021 code is correct and staff recommendation is to delete the change from the agency's rules and revert to the published code language.