District: <u>Sunbeam Family Services</u> School: <u>Harbison Early Education Center</u> Sampling Date: 10/10/2024

Status: Remediation

RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at Sunbeam Family Services - Harbison Early Education Center on October 10, 2024. Overall, thirteen (13) outlets were tested resulting in a total of twenty-six (26) samples being sent to the lab.

- Twenty-three (23) samples had no detectable level of lead.
- Three (3) samples had a low detection of lead between 1.0 and 14.9 μ g/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 μg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as $\mu g/L$. For more information on how to read this report, please see our **Results Interpretation** Fact Sheet.

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action			
		Initial Sampling					
Non-Detect (<1.0 μg/L)							
1-1-1-CF1	Classroom faucet in Classroom 1; tall sink to right	<1.0	<1.0	N/A			
1-1-1-CF2	Classroom faucet in Classroom 1; tall sink to left	<1.0	<1.0	N/A			
1-1-1-CF3	Classroom faucet in Classroom 1; small sink	<1.0	<1.0	N/A			
1-1-2-CF1	Classroom faucet in Classroom 2; small sink	<1.0	<1.0	N/A			
1-1-2-CF2	Classroom faucet in Classroom 2; tall sink to right	<1.0	<1.0	N/A			
1-1-2-BF1	Bathroom faucet in Classroom 2 Bathroom	<1.0	<1.0	N/A			
1-1-3-CF1	Classroom faucet in Classroom 3; tall sink to left	<1.0	<1.0	N/A			
1-1-3-CF2	Classroom faucet in Classroom 3; tall sink to right	<1.0	<1.0	N/A			
1-1-3-BF1	Bathroom faucet in Classroom 3 Bathroom	<1.0	<1.0	N/A			
1-1-KIT-IM1	Scotsman ice machine in kitchen	<1.0	<1.0	N/A			
1-1-PLAY-OF1	Outdoor faucet on playground; used for water play	<1.0	<1.0	N/A			

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action		
		Initial Sampling				
Low Detection (1.0 - 14.9 μg/L)						
1-1-HALL-DW2	Elkay drinking water station in main hallway; right side	1.0	<1.0			
1-1-HALL-DW1	Elkay drinking water station in main hallway; left side	1.8	0.9			