



OKLAHOMA DRINKING WATER

LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Cherokee Nation Stilwell Child Development Center Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma
Lead in Schools and Child Care Program (LWSC) on 06/16/2026
from 398 North Eighth Street, Stilwell, OK 74960.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:

CF: Classroom Faucet

KF: Kitchen Faucet

BF: Bathroom Faucet

NS: Nurse Office Sink

RA: Refrigerator Appliance

OF: Outdoor Faucet

IM: Ice Machine

DW: Drinking Water Fountain

WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	1918-1	1	1	Kitchen	KF		Two compartments, back of kitchen, PUR filter	<1 ppb	<1 ppb	06/16/2026 05:27	No Further Action	
2	1918-2	1	1	Kitchen	KF		Pot filler	<1 ppb	<1 ppb	06/16/2026 05:27	No Further Action	
3	1918-3	1	1	Deer room	CF		Short faucet	<1 ppb	<1 ppb	06/16/2026 05:27	No Further Action	
4	1918-5	1	1	Bear room	CF		Tall faucet, right of fridge	<1 ppb	<1 ppb	06/16/2026 05:27	No Further Action	
5	1918-6	1	1	Between 2 and 3	WC	ELKAY EZH2O, LZSTL8WSLP	Right bottle filler, filter red	<1 ppb	<1 ppb	06/16/2026 05:27	No Further Action	
6	1918-4	1	1	Deer room	CF		Tall faucet, right of fridge	<1 ppb	<1 ppb	06/16/2026 05:27	No Further Action	
7	1918-10	1	1	Across from room 1 and 2	IM		Fridge ice machine	<1 ppb		06/16/2026 05:50	No Further Action	
8	1918-7	1	1	Between 2 and 3	WC	ELKAY EZH2O, LZSTL8WSLP	Right fountain	<1 ppb	<1 ppb	06/16/2026 05:27	No Further Action	
9	1918-9	1	1	Across from room 1 and 2	CF		2 compartments, left of fridge, PUR filter	<1 ppb	<1 ppb	06/16/2026 05:27	No Further Action	
10	1918-8	1	1	Between 2 and 3	WC	ELKAY EZH2O, LZSTL8WSLP	Left fountain	<1 ppb	<1 ppb	06/16/2026 05:27	No Further Action	
11	1918-11	1	1	1	CF		2 compartments faucet, PUR filter	<1 ppb	<1 ppb	06/16/2026 05:52	No Further Action	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
12	1918-13	1	1	2	CF		2 compartment, tall faucet	<1 ppb	<1 ppb	06/16/2026 05:52	No Further Action	
13	1918-12	1	1	2	CF		1 compartment, small faucet	<1 ppb	<1 ppb	06/16/2026 05:52	No Further Action	
14	1918-14	1	1	3	CF		2 compartment faucet, PUR filter	<1 ppb	<1 ppb	06/16/2026 05:52	No Further Action	
15	1918-15	1	1	Wolf room	CF		Short faucet	<1 ppb	<1 ppb	06/16/2026 05:52	No Further Action	
16	1918-16	1	1	Wolf room	CF		Tall faucet, right of fridge	<1 ppb	<1 ppb	06/16/2026 05:52	No Further Action	
17	1918-17	1	1	Cub room	CF		Short faucet	<1 ppb	<1 ppb	06/16/2026 05:52	No Further Action	
18	1918-20	1	1	Eagles room	CF		Short faucet	<1 ppb	<1 ppb	06/16/2026 05:52	No Further Action	
19	1918-19	1	1	Blue bird room	CF		Tall faucet, right of fridge	<1 ppb	<1 ppb	06/16/2026 05:52	No Further Action	
20	1918-18	1	1	Blue birds room	CF		Short faucet	<1 ppb	<1 ppb	06/16/2026 05:52	No Further Action	
21	1918-21	1	1	Blue bird room	CF		Across from bathroom	<1 ppb	<1 ppb	06/16/2026 05:52	No Further Action	
22	1918-23	1	1	Kitchen	IM	MANITOWOC	Middle of kitchen, across from oven	<1 ppb		06/16/2026 06:06	No Further Action	
23	1918-24	1	1	Kitchen	KF		Front of kitchen, across from oven	<1 ppb	<1 ppb	06/16/2026 06:10	No Further Action	

[illegible]