



OKLAHOMA DRINKING WATER

LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Pawnee Nation Cdc Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma
Lead in Schools and Child Care Program (LWSC) on 09/01/2026
from 804 MORRIS RD, Pawnee, OK 74058.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:

CF: Classroom Faucet

KF: Kitchen Faucet

BF: Bathroom Faucet

NS: Nurse Office Sink

RA: Refrigerator Appliance

OF: Outdoor Faucet

IM: Ice Machine

DW: Drinking Water Fountain

WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	2178-1	1	1	Kitchen	KF		Sink to the right	7.13 ppb	<1 ppb	09/01/2026 07:00	Remediation Recommended	
2	2178-5	1	1	Hallway	WC	Elkay-EZFS8_1A	Outside Ms. Dana's classroom	4.31 ppb	2.7 ppb	09/01/2026 07:00	Remediation Recommended	
3	2178-18	1	1	Kitchen	KF		Kitchen area to the right of infants classroom	3.97 ppb	<1 ppb	09/01/2026 07:00	Remediation Recommended	
4	2178-2	1	1	Kitchen	KF		Sink to the left	3.29 ppb	<1 ppb	09/01/2026 07:00	Remediation Recommended	
5	2178-17	1	1	Outside infants classroom	DW	Oasis	Water fountain to the top left outside infants classroom, right bottom one not working	2.93 ppb	2.46 ppb	09/01/2026 07:00	Remediation Recommended	
6	2178-11	1	1	Bathroom	BF		Bathroom (Men's)- Sink to the left	2.01 ppb	<1 ppb	09/01/2026 07:00	Remediation Recommended	
7	2178-15	1	1	Classroom	CF		Toddler's classroom sink to the right	1.89 ppb	<1 ppb	09/01/2026 07:00	Remediation Recommended	
8	2178-4	1	1	Bathroom	BF		Ms. Dana's classroom - bathroom to the right	1.69 ppb	<1 ppb	09/01/2026 07:00	Remediation Recommended	
9	2178-16	1	1	Classroom	CF		Infants classroom	1.68 ppb	<1 ppb	09/01/2026 07:00	Remediation Recommended	
10	2178-8	1	1	Classroom	CF		Ms. Talia's Classroom sink to the right when we enter	1.57 ppb	<1 ppb	09/01/2026 07:00	Remediation Recommended	

#	Outlet ID	Buildin g #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
11	2178-13	1	1	Bathroom	BF		Bathroom (Women's) - Sink to the left	1.55 ppb	<1 ppb	09/01/2026 07:00	Remediation Recommended	
12	2178-7	1	1	Classroom	CF		Ms. Talia's Classroom	1.47 ppb	<1 ppb	09/01/2026 07:00	Remediation Recommended	
13	2178-3	1	1	Bathroom	BF		Ms.Dana's classroom - bathroom to the left	1.2 ppb	<1 ppb	09/01/2026 07:00	Remediation Recommended	
14	2178-12	1	1	Bathroom	BF		Bathroom (Men's)- Sink to the right	1.15 ppb	<1 ppb	09/01/2026 07:00	Remediation Recommended	
15	2178-6	1	1	Classroom	CF		Ms. Vickie's Classroom (Center one)	<1 ppb	<1 ppb	09/01/2026 07:00	No Further Action	
16	2178-9	1	1	Cafeteria	KF		Dining area behind the big classroom	<1 ppb	<1 ppb	09/01/2026 07:00	No Further Action	
17	2178-10	1	1	Cafeteria	RA	Crosley	Dining area behind the big classroom Filter status red	<1 ppb	<1 ppb	09/01/2026 07:00	No Further Action	
18	2178-14	1	1	Bathroom	BF		Bathroom (Women's) - Sink to the right	<1 ppb	<1 ppb	09/01/2026 07:00	No Further Action	