



OKLAHOMA DRINKING WATER

LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Oakridge Es Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma
Lead in Schools and Child Care Program (LWSC) on 07/24/2026
from 3201 South Santa Fe, Moore, OK 73160.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:

CF: Classroom Faucet

KF: Kitchen Faucet

BF: Bathroom Faucet

NS: Nurse Office Sink

RA: Refrigerator Appliance

OF: Outdoor Faucet

IM: Ice Machine

DW: Drinking Water Fountain

WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	3449-2	1	1	Cafetorium	KF		Pot filler	1.17 ppb	<1 ppb	07/24/2026 06:43	Remediation Recommended	
2	3449-3	1	1	Cafetorium	IM		Ice machine	<1 ppb		07/24/2026 06:49	No Further Action	
3	3449-4	1	1	Cafetorium	WC	Elkay ezfs8_1C	Left tell fountain	<1 ppb	<1 ppb	07/24/2026 06:52	No Further Action	
4	3449-1	1	1	Cafetorium	KF		Dish sink	<1 ppb	<1 ppb	07/24/2026 06:42	No Further Action	
5	3449-5	1	1	Cafetorium	WC	Elkay ezfs8_1C	Right short fountain	<1 ppb	<1 ppb	07/24/2026 06:54	No Further Action	
6	3449-10	1	1	Next to custodian A room	WC	Elkay ezfs8_1C	Fountain below bottle filler, in between set of fountains	<1 ppb	<1 ppb	07/24/2026 07:04	No Further Action	
7	3449-7	1	1	Across from Cafetorium	WC	Elkay ezfs8_1C	Right short fountain	<1 ppb	<1 ppb	07/24/2026 06:58	No Further Action	
8	3449-9	1	1	Next to custodian A room	WC	EZH20	Bottle filler in between set of fountains	<1 ppb	<1 ppb	07/24/2026 07:03	No Further Action	
9	3449-8	1	1	Next to custodian A room	WC	Elkay	Left short fountain	<1 ppb	<1 ppb	07/24/2026 07:00	No Further Action	
10	3449-6	1	1	Across from Cafetorium	WC	Elkay ezfs8_1C	Left tall fountain	<1 ppb	<1 ppb	07/24/2026 06:57	No Further Action	
11	3449-11	1	1	Next to custodian A room	WC	Elkay	Short fountain	<1 ppb	<1 ppb	07/24/2026 07:07	No Further Action	
12	3449-12	1	1	Next to custodian B room	WC	Elkay	Left tall fountain	<1 ppb	<1 ppb	07/24/2026 07:09	No Further Action	
13	3449-15	1	1	Between gym and custodian C room	WC	EZH20	Bottle filler on top of fountain	<1 ppb	<1 ppb	07/24/2026 07:15	No Further Action	

[illegible]