OKLAHOMA DRINKING WATER
LEAD TESTING
IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Liberty Es
Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma Lead in Schools and Child Care Program (LWSC) on 10/01/2026 from 505 West Liberty, Ponca City, OK 74601.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:
CF: Classroom Faucet
KF: Kitchen Faucet
BF: Bathroom Faucet
NS: Nurse Office Sink
RA: Refrigerator Appliance
OF: Outdoor Faucet
IM: Ice Machine
DW: Drinking Water Fountain
WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	3806-12	1	1	Near the Gym - Entrance	WC	Elkay	Water fountain	<1 ppb	2.4 ppb	10/01/2026 05:30	Remediation Recommended	
2	3806-10	1	1	Hallway near Room 119	WC	Elkay	Center, Water Fountain	<1 ppb	2.03 ppb	10/01/2026 05:30	Remediation Recommended	
3	3806-1	1	1	Across Room 116	WC	Elkay ezH2O	Left Side, Water Fountain	<1 ppb	<1 ppb	10/01/2026 05:30	No Further Action	
4	3806-2	1	1	Across Room 116	WC	Elkay ezH2O	Right Side, Water Fountain	<1 ppb	<1 ppb	10/01/2026 05:30	No Further Action	
5	3806-3	1	1	Between Rooms C4 and B4	WC	Elkay ezH2O	Left Side, Water Fountain	<1 ppb	<1 ppb	10/01/2026 05:30	No Further Action	
6	3806-4	1	1	Between Rooms C4 and B4	WC	Elkay ezH2O	Center, Water Fountain	<1 ppb	<1 ppb	10/01/2026 05:30	No Further Action	
7	3806-5	1	1	Between Rooms C4 and B4	WC	Elkay ezH2O	Right Side, Water Fountain	<1 ppb	<1 ppb	10/01/2026 05:30	No Further Action	
8	3806-6	1	1	Classroom C4	DW		Water fountain	<1 ppb	<1 ppb	10/01/2026 05:30	No Further Action	
9	3806-7	1	1	Classroom 2	DW		Water fountain	<1 ppb	<1 ppb	10/01/2026 05:30	No Further Action	
10	3806-8	1	1	Main Office	IM	Scotsman	IM	<1 ppb		10/01/2026 05:30	No Further Action	
11	3806-9	1	1	Main Office	CF		Sink	<1 ppb	<1 ppb	10/01/2026 05:30	No Further Action	
12	3806-11	1	1	Hallway near Room 119	WC	Elkay ezH2O	Right Side, Water Fountain	<1 ppb	<1 ppb	10/01/2026 05:30	No Further Action	
13	3806-13	1	1	Back side of Gym	WC	Elkay	Water fountain	<1 ppb	<1 ppb	10/01/2026 05:30	No Further Action	
14	3806-14	1	1	To the left of Room 102	WC	Elkay	Left Side, Water fountain	<1 ppb	<1 ppb	10/01/2026 05:30	No Further Action	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
15	3806-15	1	1	To the left of Room 102	WC	Elkay	Right Side, Water fountain	<1 ppb	<1 ppb	10/01/2026 05:30	No Further Action	