OKLAHOMA DRINKING WATER
LEAD TESTING
IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Garfield Es
Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma Lead in Schools and Child Care Program (LWSC) on 09/29/2026 from 600 South 8Th Street, Ponca City, OK 74601.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:
CF: Classroom Faucet
KF: Kitchen Faucet
BF: Bathroom Faucet
NS: Nurse Office Sink
RA: Refrigerator Appliance
OF: Outdoor Faucet
IM: Ice Machine
DW: Drinking Water Fountain
WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	3812-1	1	1	Resource Room-Cafeteria	IM	Manitowoc	Teacher's Lounge	<1 ppb		9/29/26 6:30	No Further Action	
2	3812-2	1	1	To the right of 2nd grade classroom	WC	Elkay	Left side, water fountain	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	
3	3812-3	1	1	To the right of 2nd grade classroom	WC	Elkay	Right side, water fountain	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	
4	3812-4	1	1	Room 108	DW		Left side, water fountain	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	
5	3812-5	1	1	Room 108	CF		Classroom Sink	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	
6	3812-6	1	1	Room 109	DW		Left side, water fountain	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	
7	3812-7	1	1	Room 109	CF		Classroom Sink	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	
8	3812-8	1	1	Room 111	DW		Right side, water fountain	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	
9	3812-9	1	1	Room 111	CF		Classroom Sink	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	
10	3812-10	1	1	Room 112	DW		Left side, water fountain	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	
11	3812-11	1	1	Room 112	CF		Classroom Sink	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	
12	3812-12	1	1	Room 114	DW		Left side, water fountain	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	
13	3812-13	1	1	Room 114	CF		Classroom Sink	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
14	3812-14	1	1	To the right of 5th grade classroom	WC	Elkay	Left side, water fountain	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	
15	3812-15	1	1	To the right of 5th grade classroom	WC	Elkay	Right side, water fountain	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	
16	3812-16	1	1	WC at the entrance of the Cafeteria, in the middle of the restrooms	WC	Elkay	Water fountain	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	
17	3812-17	1	1	WC in the Cafeteria	WC	Elkay	Water fountain	<1 ppb	<1 ppb	9/29/26 6:30	No Further Action	