



OKLAHOMA DRINKING WATER

**LEAD TESTING**

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

## Western Gateway Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma Lead in Schools and Child Care Program (LWSC) on 08/06/2026 from 1300 Sw 15Th Street, Oklahoma City, OK 73108.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:

CF: Classroom Faucet

KF: Kitchen Faucet

BF: Bathroom Faucet

NS: Nurse Office Sink

RA: Refrigerator Appliance

OF: Outdoor Faucet

IM: Ice Machine

DW: Drinking Water Fountain

WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

| #  | Outlet ID | Building # | Floor # | Room # / Name                | Outlet Type Code | Water Cooler Make and Model | Comments            | Initial First Draw Result Final (ppb) | Initial Flush Draw Result Final (ppb) | Initial Sample Date(s) | Action Needed?          | Remediation Action Taken |
|----|-----------|------------|---------|------------------------------|------------------|-----------------------------|---------------------|---------------------------------------|---------------------------------------|------------------------|-------------------------|--------------------------|
| 1  | 4095-6    | 1          | 1       | Classroom 127                | CF               |                             |                     | 4.4 ppb                               | <1 ppb                                | 08/06/2026 06:30       | Remediation Recommended |                          |
| 2  | 4095-30   | 1          | 1       | Kitchen 2 bay sink on island | KF               |                             |                     | 2.66 ppb                              | <1 ppb                                | 08/06/2026 06:30       | Remediation Recommended |                          |
| 3  | 4095-33   | 1          | 1       | Nurse's office               | NS               |                             |                     | 2.58 ppb                              | <1 ppb                                | 08/06/2026 06:30       | Remediation Recommended |                          |
| 4  | 4095-31   | 1          | 1       | Kitchen sink on island       | KF               |                             |                     | 2.41 ppb                              | <1 ppb                                | 08/06/2026 06:30       | Remediation Recommended |                          |
| 5  | 4095-3    | 1          | 1       | Classroom 125                | CF               |                             |                     | 2.09 ppb                              | <1 ppb                                | 08/06/2026 06:30       | Remediation Recommended |                          |
| 6  | 4095-16   | 1          | 1       | Classroom 141                | CF               |                             |                     | 1.76 ppb                              | <1 ppb                                | 08/06/2026 06:30       | Remediation Recommended |                          |
| 7  | 4095-25   | 1          | 1       | Classroom 159                | CF               |                             |                     | 1.6 ppb                               | <1 ppb                                | 08/06/2026 06:30       | Remediation Recommended |                          |
| 8  | 4095-8    | 1          | 1       | Classroom 131                | CF               |                             |                     | 1.58 ppb                              | <1 ppb                                | 08/06/2026 06:30       | Remediation Recommended |                          |
| 9  | 4095-26   | 1          | 1       | Classroom 161                | CF               |                             |                     | 1.47 ppb                              | <1 ppb                                | 08/06/2026 06:30       | Remediation Recommended |                          |
| 10 | 4095-15   | 1          | 1       | Classroom 138                | CF               |                             |                     | 1.34 ppb                              | <1 ppb                                | 08/06/2026 06:30       | Remediation Recommended |                          |
| 11 | 4095-14   | 1          | 1       | Classroom 139                | CF               |                             |                     | 1.26 ppb                              | <1 ppb                                | 08/06/2026 06:30       | Remediation Recommended |                          |
| 12 | 4095-21   | 1          | 1       | Classroom 155                | CF               |                             |                     | 1.21 ppb                              | <1 ppb                                | 08/06/2026 06:30       | Remediation Recommended |                          |
| 13 | 4095-7    | 1          | 1       | Classroom 129                | CF               |                             |                     | 1.1 ppb                               | <10 ppb                               | 08/06/2026 06:30       | Remediation Recommended |                          |
| 14 | 4095-1    | 1          | 1       | Classroom 121                | CF               |                             |                     | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action       |                          |
| 15 | 4095-5    | 1          | 1       | Hallway between 125 & 127    | WC               | Murdock                     | Lower left fountain | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action       |                          |
| 16 | 4095-2    | 1          | 1       | Classroom 123                | CF               |                             |                     | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action       |                          |

| #  | Outlet ID | Building # | Floor # | Room # / Name                                     | Outlet Type Code | Water Cooler Make and Model | Comments             | Initial First Draw Result Final (ppb) | Initial Flush Draw Result Final (ppb) | Initial Sample Date(s) | Action Needed?    | Remediation Action Taken |
|----|-----------|------------|---------|---------------------------------------------------|------------------|-----------------------------|----------------------|---------------------------------------|---------------------------------------|------------------------|-------------------|--------------------------|
| 17 | 4095-4    | 1          | 1       | Hallway between class 125 & 127                   | WC               | Murdock                     | Upper right fountain | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
| 18 | 4095-10   | 1          | 1       | Lounge Room 132 fridge                            | RA               | ThinQ LG                    |                      | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
| 19 | 4095-9    | 1          | 1       | Lounge Room 132 kitchen faucet                    | KF               |                             |                      | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
| 20 | 4095-12   | 1          | 1       | Classroom 135                                     | CF               |                             |                      | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
| 21 | 4095-13   | 1          | 1       | Classroom 137                                     | CF               |                             |                      | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
| 22 | 4095-17   | 1          | 1       | Hallway outside and to the right of classroom 145 | WC               | Murdock                     | Upper right fountain | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
| 23 | 4095-18   | 1          | 1       | Hallway outside and to the right of classroom 145 | WC               | Murdock                     | Lower left fountain  | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
| 24 | 4095-19   | 1          | 1       | Classroom 145                                     | CF               |                             |                      | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
| 25 | 4095-20   | 1          | 1       | Classroom 153                                     | CF               |                             |                      | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
| 26 | 4095-22   | 1          | 1       | Classroom 157                                     | CF               |                             |                      | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
| 27 | 4095-24   | 1          | 1       | Hallway between classroom 157 and 159             | WC               | Murdock                     | Lower left fountain  | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
| 28 | 4095-23   | 1          | 1       | Hallway between classroom 157 and 159             | WC               | Murdock                     | Upper right fountain | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |

| #  | Outlet ID | Building # | Floor # | Room # / Name                 | Outlet Type Code | Water Cooler Make and Model | Comments             | Initial First Draw Result Final (ppb) | Initial Flush Draw Result Final (ppb) | Initial Sample Date(s) | Action Needed?    | Remediation Action Taken |
|----|-----------|------------|---------|-------------------------------|------------------|-----------------------------|----------------------|---------------------------------------|---------------------------------------|------------------------|-------------------|--------------------------|
| 29 | 4095-27   | 1          | 1       | Classroom 163                 | CF               |                             |                      | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
| 30 | 4095-28   | 1          | 1       | Cafeteria                     | WC               | Murdock                     | Lower left fountain  | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
| 31 | 4095-29   | 1          | 1       | Cafeteria                     | WC               | Murdock                     | Upper right fountain | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
| 32 | 4095-32   | 1          | 1       | Kitchen ice machine           | IM               | Manitowoc                   |                      | <1 ppb                                |                                       | 08/06/2026 06:30       | No Further Action |                          |
| 33 | 4095-11   | 1          | 1       | Hallway next to classroom 135 | WC               | Murdock                     |                      | <1 ppb                                | <1 ppb                                | 08/06/2026 06:30       | No Further Action |                          |
|    |           |            |         |                               |                  |                             |                      |                                       |                                       |                        |                   |                          |