OKLAHOMA DRINKING WATER
LEAD TESTING
IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Soldier Creek Es
Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma Lead in Schools and Child Care Program (LWSC) on 10/08/2026 from 9021 Se 15Th Street, Midwest City, OK 73130.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:
CF: Classroom Faucet
KF: Kitchen Faucet
BF: Bathroom Faucet
NS: Nurse Office Sink
RA: Refrigerator Appliance
OF: Outdoor Faucet
IM: Ice Machine
DW: Drinking Water Fountain
WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	4218-5	1	1	Gym	WC	Elkay ezH2O	WF on extreme right	1.53 ppb	<1 ppb	10/08/2026 06:00	Remediation Recommended	
2	4218-3	1	1	Gym	WC	Elkay ezH2O	BF 3rd from left	<1 ppb	1.41 ppb	10/08/2026 06:00	Remediation Recommended	
3	4218-2	1	1	Gym	WC	Elkay ezH2O	WF 2nd from left	<1 ppb	1.36 ppb	10/08/2026 06:00	Remediation Recommended	
4	4218-4	1	1	Gym	WC	Elkay ezH2O	WF 3rd from left	<1 ppb	1.27 ppb	10/08/2026 06:00	Remediation Recommended	
5	4218-1	1	1	Gym	WC	Elkay ezH2O	WC on the extreme left	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
6	4218-10	1	1	C109	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
7	4218-8	1	1	C113	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
8	4218-7	1	1	C115	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
9	4218-9	1	1	C112	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
10	4218-6	1	1	C116	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
11	4218-13	1	1	Across from the Cafeteria	WC	Elkay ezH2O	WF in the center	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
12	4218-15	1	1	D100	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
13	4218-14	1	1	Across from the Cafeteria	WC	Elkay ezH2O	WF to the right	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
14	4218-12	1	1	Across from the Cafeteria	WC	Elkay ezH2O	BF in the center- filter status red	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
15	4218-11	1	1	Across from the Cafeteria	WC	Elkay ezH2O	WF on the extreme left	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
16	4218-17	1	1	D104	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
17	4218-20	1	1	E108	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
18	4218-19	1	1	D107	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
19	4218-18	1	1	D106	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
20	4218-16	1	1	D103	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
21	4218-23	1	1	E102	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
22	4218-24	1	1	E104	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
23	4218-25	1	1	E107	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
24	4218-22	1	1	E113	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
25	4218-21	1	1	E111	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
26	4218-28	1	1	A130	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
27	4218-26	1	1	A125	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
28	4218-29	1	1	Kitchen	IM	Manitowoc	IM in the front	<1 ppb		10/08/2026 06:00	No Further Action	
29	4218-27	1	1	A126	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
30	4218-30	1	1	Kitchen	KF		Sink in the cooking area	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
31	4218-34	1	2	C214	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
32	4218-32	1	2	C211	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
33	4218-35	1	2	C215	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
34	4218-31	1	2	C208	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
35	4218-33	1	2	C212	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
36	4218-37	1	2	B208	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
37	4218-40	1	2	D203	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
38	4218-36	1	2	C218	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
39	4218-39	1	2	D200	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
40	4218-38	1	2	B206	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
41	4218-44	1	2	D210	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
42	4218-42	1	2	D206	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
43	4218-41	1	2	D204	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
44	4218-45	1	2	A208	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
45	4218-43	1	2	D207	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
46	4218-46	1	2	A203	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
47	4218-47	1	2	E200	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
48	4218-49	1	2	E205	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
49	4218-48	1	2	E203	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
50	4218-50	1	2	E206	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
51	4218-51	1	2	E208	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
52	4218-52	1	2	E211	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
53	4218-53	1	2	A209	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	
54	4218-54	1	2	A211	DW		WF to the right of the sink	<1 ppb	<1 ppb	10/08/2026 06:00	No Further Action	