



OKLAHOMA DRINKING WATER

LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

Plato Es Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma
Lead in Schools and Child Care Program (LWSC) on 06/10/2026
from 1011 W. Plato Road, Duncan, OK 73533.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:

CF: Classroom Faucet

KF: Kitchen Faucet

BF: Bathroom Faucet

NS: Nurse Office Sink

RA: Refrigerator Appliance

OF: Outdoor Faucet

IM: Ice Machine

DW: Drinking Water Fountain

WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

#	Outlet ID	Building #	Floor #	Room # / Name	Outlet Type Code	Water Cooler Make and Model	Comments	Initial First Draw Result Final (ppb)	Initial Flush Draw Result Final (ppb)	Initial Sample Date(s)	Action Needed?	Remediation Action Taken
1	4612-10	1	1	27	CF		Right faucet	4.09 ppb	1.41 ppb	6/10/2026 8:10:00 AM	Remediation Recommended	
2	4612-12	1	1	29	CF		Left side, left faucet	3.35 ppb	<1 ppb	6/10/2026 8:10:00 AM	Remediation Recommended	
3	4612-16	1	1	30	CF		Left side, left faucet	3.22 ppb	<1 ppb	6/10/2026 8:10:00 AM	Remediation Recommended	
4	4612-6	1	1	23	CF		Right faucet	<1 ppb	2.47 ppb	6/10/2026 7:50:00 AM	Remediation Recommended	
5	4612-11	1	1	27	DW		Left bubbler	2.26 ppb	<1 ppb	6/10/2026 8:10:00 AM	Remediation Recommended	
6	4612-18	1	1	30	CF		Right side, left faucet	2.15 ppb	<1 ppb	6/10/2026 8:10:00 AM	Remediation Recommended	
7	4612-17	1	1	30	DW		Left side, right bubbler	2.12 ppb	<1 ppb	6/10/2026 8:10:00 AM	Remediation Recommended	
8	4612-15	1	1	29	DW		Right side, right bubbler	1.89 ppb	<1 ppb	6/10/2026 8:10:00 AM	Remediation Recommended	
9	4612-14	1	1	29	CF		Right side, left faucet	1.88 ppb	<1 ppb	6/10/2026 8:10:00 AM	Remediation Recommended	
10	4612-13	1	1	29	DW		Left side, right bubbler	1.33 ppb	<1 ppb	6/10/2026 8:10:00 AM	Remediation Recommended	
11	4612-19	1	1	30	DW		Right side, right bubbler	1.04 ppb	<1 ppb	6/10/2026 8:10:00 AM	Remediation Recommended	
12	4612-1	1	1	Between rooms 13 and 9	WC	ELAKY EZH2O	Bottle filler	<1 ppb	<1 ppb	6/10/2026 7:50:00 AM	No Further Action	
13	4612-2	1	1	Between rooms 13 and 9	WC	ELKAY LZS8WSLP	Fountain	<1 ppb	<1 ppb	6/10/2026 7:50:00 AM	No Further Action	
14	4612-3	1	1	Gym	WC	ELKAY EZFS8_1H	Single fountain left corner	<1 ppb	<1 ppb	6/10/2026 7:50:00 AM	No Further Action	

[illegible]