



OKLAHOMA DRINKING WATER

LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

District: Anadarko Public School District

School: Anadarko Middle School

Sampling Date: 6/5/2025

Status: Remediation

RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at Anadarko Public School District – Anadarko Middle School on June 5, 2025. Overall, twenty-nine (29) outlets were tested resulting in a total of fifty-eight (58) samples being sent to the lab.

- Forty-eight (48) samples had no detectable level of lead.
- Eight (8) samples had a low detection of lead between 1.0 and 14.9 µg/L.
- Two (2) samples had a high detection of lead equal to or above 15.0 µg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as µg/L. For more information on how to read this report, please see our **Results Interpretation Fact Sheet**.

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
Non-Detect (<1.0 µg/L)				
1-1-HALL-DW1	Fountain across from room 44- Hall	<1.0	<1.0	N/A
1-1-HALL-WC1	Bottle filler across from room 12- Hall	<1.0	<1.0	N/A
1-1-HALL-WC2	Fountain across room 12- Hall	<1.0	<1.0	N/A
1-1-CAFÉ-IM1	Cafeteria ice machine Scotsman	<1.0	<1.0	N/A
1-1-HALL-WC3	Hall water cooler across from boiler room	<1.0	<1.0	N/A
1-1-HALL-WC4	Hall Right water cooler across from boiler room	<1.0	<1.0	N/A
1-1-38-CF1	CF room 38	<1.0	<1.0	N/A
1-1-38-DW1	Fountain in room 38	<1.0	<1.0	N/A
1-1-37-CF1	CF in room 37	<1.0	<1.0	N/A
1-1-37-CF2	Fountain in room 37	<1.0	<1.0	N/A
1-1-34-CF1	CF in room 34	<1.0	<1.0	N/A
1-1-34-DW1	Fountain in room 34	<1.0	<1.0	N/A
1-1-HALL-WC5	Bottle Filler in Hall across from library	<1.0	<1.0	N/A
1-1-HALL-WC6	Water fountain under bottle filler in Hall across from library	<1.0	<1.0	N/A

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
1-1-17-DW1	Hall fountain across from room 17	<1.0	<1.0	N/A
1-1-TL-KF1	Teachers' lounge kitchen faucet right	<1.0	<1.0	N/A
1-1-MAIN-KF1	Main office kitchen faucet	<1.0	<1.0	N/A
3-1-GB-BF1	Tech ed building girls bathroom faucet	<1.0	<1.0	N/A
3-1-HALL-WC1	Hall Tech ed building BOTTLE Filler between men and women's restroom	<1.0	<1.0	N/A
3-1-HALL-WC2	Hall Tech ed building WATER Cooler between men and women's restroom	<1.0	<1.0	N/A
Low Detection (1.0 - 14.9 µg/L)				
3-1-BB-BF1	Tech-ed building men's bathroom faucet	1.2	<1.0	
1-1-28-CF1	Faucet in room 28	1.3	<1.0	
1-1-TL-KF2	Teachers' lounge kitchen faucet left	2.3	<1.0	
2-1-BB-BF1	Ag building men's bathroom faucet across from office	2.3	<1.0	
1-1-KIT-KF2	Kitchen pot filler	2.6	<1.0	
2-1-GB-BF1	Ag building girl's bathroom faucet across from office	3.5	<1.0	
1-1-25-CF1	Faucet in room 25	4.1	<1.0	
High Detection (≥15.0 µg/L)				
3-1-SHOP-DW1	Water fountain next to cooler and pamphlets in Shop	10.8	24.5	
1-1-KIT-KF1	Kitchen sprayer	50.5	<1.0	