



OKLAHOMA DRINKING WATER

# LEAD TESTING

IN PUBLIC SCHOOLS &amp; CHILD CARE FACILITIES

District: Wetumka Public Schools  
School: Wetumka Elementary School  
Sampling Date: 7/15/2025  
Status: Remediation

## RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at Wetumka Public Schools - Wetumka Elementary School on July 15, 2025. Overall, fifteen (15) outlets were tested resulting in a total of thirty (30) samples being sent to the lab.

- Twenty-three (23) samples had no detectable level of lead.
- Seven (7) samples had a low detection of lead between 1.0 and 14.9 µg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 µg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as µg/L. For more information on how to read this report, please see our **Results Interpretation Fact Sheet**.

| Sample ID                       | Outlet Description   | First Draw<br>(µg/L) | Flush<br>(µg/L) | Remedial Action |
|---------------------------------|--|----------------------|-----------------|-----------------|
|                                 |  | Initial Sampling     |                 |                 |
| Non-Detect (<1.0 µg/L)          |  |                      |                 |                 |
| 1-1-HALL-WC1                    | Hall (between room 2 and 3) - top left bottle filler                       | <1.0                 | <1.0            | N/A             |
| 1-1-HALL-WC2                    | Hall (between room 2 and 3) - left bottom water cooler                     | <1.0                 | <1.0            | N/A             |
| 1-1-HALL-WC3                    | Hall (between room 2 and 3) - top right bottle filler                      | <1.0                 | <1.0            | N/A             |
| 1-1-MR-CF2                      | Mailroom room 7 - sprayer attached to room faucet                          | <1.0                 | <1.0            | N/A             |
| 1-1-HALL-WC5                    | Hall left of electrical room across from room 11 - top right bottle filler | <1.0                 | <1.0            | N/A             |
| 1-1-HALL-WC6                    | Hall left of electrical room across from room 11- left bottom              | <1.0                 | <1.0            | N/A             |
| 1-1-HALL-WC7                    | Hall left of electrical room across from room 11 - top right bottle filler | <1.0                 | <1.0            | N/A             |
| 1-1-HALL-WC8                    | Hall left of electrical room across from room 11 - right bottom            | <1.0                 | <1.0            | N/A             |
| 2-1-KIT-KF1                     | Kitchen in cafeteria - 3 compartment sink right faucet                     | <1.0                 | <1.0            | N/A             |
| 2-1-KIT-IM1                     | Kitchen icemachine behind lunch line                                       | <1.0                 | <1.0            | N/A             |
| Low Detection (1.0 - 14.9 µg/L) |  |                      |                 |                 |
| 2-1-KIT-KF2                     | Kitchen in cafeteria - 3 compartment sink left faucet                      | 1.3                  | <1.0            |                 |

| Sample ID    | Outlet Description                                      | First Draw<br>(µg/L) | Flush<br>(µg/L) | Remedial<br>Action |
|--------------|---|----------------------|-----------------|--------------------|
|              |   | Initial Sampling     |                 |                    |
| 2-1-CAFÉ-WC1 | Cafeteria top right bottle filler                       | 2.1                  | 3.0             |                    |
| 2-1-KIT-KF3  | Kitchen in cafeteria- faucet left of 3 compartment sink | 4.0                  | <1.0            |                    |
| 1-1-MR-CF1   | Mailroom room 7 - room faucet left back wall            | 4.7                  | <1.0            |                    |
| 1-1-HALL-WC4 | Hall in front of main office - bottom left water cooler | 5.3                  | 1.4             |                    |